

INSPECTION REPORT


End of contract

GENERAL INFO

File	317622
License plate	2EHU839
Vehicle identification number	VF1RHN00671790579
Dossier	2023 143 169
Make	Renault Espace ET200 Esprit AI
Mileage	82032
First registration	17/10/2023
client availability date	13/07/2026
inspectionDate	18/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
35	Front Bonnet // Polish	Y
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	N
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	N
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
540	Interior // Repair 1	N
624	Front Right Door Interior Coating // Replace Completely	Y

Damage Pictures




Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Painting-scratch



Light / Rear left / Replace-scratch




Wheel Two Tone Rear Left // Repair-scratch




Wheel Two Tone Front Left // Repair-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch




Rocker Panel Left // Smart Repair Medium-scratch + dent




Door Rear Left // Smart Repair Medium-scratch + dent



Front Bonnet / Insulation / Replace-cracked



Windshield // Repair-glass damage



Front Bonnet // Polish-Chemical reaction



Wing Front right // Polish-Chemical reaction



Interior // Repair 1-hole