



## Ford Focus: P118SH

|                         |                   |                        |                                        |
|-------------------------|-------------------|------------------------|----------------------------------------|
| Vinnumber:              | WF0PXXGCHPNY35766 | Versionname:           | Focus 1.5 Ecoblue 88kW Connected Wagon |
| First Registrationdate: | 17/06/2022        | Fiscalpower:           |                                        |
| Expertise Mileage:      | 163781            | Power Kw:              | 88                                     |
| Bodytype:               |                   | Body colour            | Frozen White                           |
| Gearbox:                | MAN 6 VIT         | Paint type             | Opaque                                 |
| Transmission:           |                   | Type of rims (mounted) | Steel                                  |
| Fueltype:               | Diesel            | Parking lot            | 551                                    |
| Number of seats         | 5                 |                        |                                        |
| Type of rims (mounted)  | Steel             |                        |                                        |
| Maintenance needed      | Yes               |                        |                                        |

## Options

|                       |   |                      |
|-----------------------|---|----------------------|
| Number of keys total  | 2 | Rear parking sensors |
| GPS                   |   | Hook                 |
| Autom climate control |   |                      |
| Radio multimedia      |   |                      |

## Tyres

| Location | Position | Measures                       | Depth  | Make        | Type   |
|----------|----------|--------------------------------|--------|-------------|--------|
| Front    | Left     | 205 / 60 / 16 / 96 / V / Steel | 5,3 mm | Bridgestone | Winter |
|          | Right    | 205 / 60 / 16 / 96 / V / Steel | 5,5 mm | Bridgestone | Winter |
| Rear     | Left     | 205 / 60 / 16 / 96 / V / Steel | 5,3 mm | Bridgestone | Winter |
|          | Right    | 205 / 60 / 16 / 96 / V / Steel | 3,5 mm | Bridgestone | Winter |

## Assistance equipment

Service, Maintenance, Execute



## Interior, Dirty, Cleaning




## Wing RL, Dent(s), Repair and paint (complete)



## Bonnet, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bodywork, Chemical polution, Polish



|                |                                             |
|----------------|---------------------------------------------|
| Kenteken       | P118SH                                      |
| Merk Model     | Ford Focus 1.5 Ecoblue 88kW Connected Wagon |
| Brandstofsoort | Diesel                                      |
| Datum deel1    | 17-06-22                                    |

| Datum reparatie | Kilometerstand | Reparatie omschrijving         |
|-----------------|----------------|--------------------------------|
| 10-06-26        | 162.957        | APK                            |
| 10-06-26        | 162.957        | Fijnstofmeting                 |
| 10-06-26        | 162.957        | Reparatie band(en)             |
| 23-12-25        | 145.909        | Riem/ multiriem                |
| 23-12-25        | 145.909        | Waterpomp                      |
| 27-11-25        | 142.758        | Onderhoudsbeurt                |
| 27-11-25        | 142.758        | Ruitenwisserblad(en) voorzijde |
| 27-11-25        | 142.758        | Sleutelbatterij                |
| 27-11-25        | 142.758        | Vervanging band                |
| 24-04-25        | 120.067        | APK                            |
| 24-04-25        | 120.067        | Fijnstofmeting                 |
| 17-04-25        | 119.868        | Vervanging band                |
| 14-02-25        | 112.960        | Reparatie band(en)             |
| 10-02-25        | 112.532        | Onderhoudsbeurt                |
| 10-02-25        | 112.532        | Remschijf + blokken achter     |
| 10-02-25        | 112.532        | Remschijf + blokken voor       |
| 19-07-24        | 86.773         | Vervanging band                |
| 01-07-24        | 84.262         | Onderhoudsbeurt                |
| 01-07-24        | 84.262         | Remvloeistof                   |
| 13-11-23        | 59.652         | Onderhoudsbeurt                |
| 13-11-23        | 59.652         | Sleutelbatterij                |
| 23-08-23        | 49.258         | Vervanging band                |
| 27-02-23        | 30.082         | Onderhoudsbeurt                |