



BMW X1 (UKL): 2CFY111

Vinnumber:	WBA71AB0305V49464	Versionname:	X1 (F48) 25e xDrive 1.5i 220pk/cv 5p Aut.
First Registrationdate:	8/07/2022	Fiscalpower:	
Expertise Mileage:	81392	Power Kw:	92
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Maintenance	dans 25000km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/50/18/99 W				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				225/50 R 18 99 W
Tyre size FR				225/50 R 18 99 W
Tyre size RL				225/50 R 18 99 W
Tyre size RR				225/50 R 18 99 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Alloy rim RL, Scratch(es), Acceptable



Door RL, Repaired, Check



Charging cable (normal), Missing, Check



Luggage compartment cover, Incomplete, Forfeit



Boot lid covering R, Scratch(es), Smart repair



Bumper R, Scratch(es), Spot repair



Bumper moulding R, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable



Kenteken	2CFY111
Merk Model	BMW X1 (F48) 25e xDrive 1.5i 220pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	7/8/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/14/26	74,757	batterij	Vervangen
4/14/26	74,757	klein materiaal	
2/20/26	72,528	injector	Vervangen
2/17/26	72,258	BMW/MINI service standaard omvang	Uitvoeren
2/17/26	72,258	BMW/MINI service voertuig-check	Uitvoeren
2/17/26	72,258	bougie	Vervangen
2/17/26	72,258	klein materiaal	
2/17/26	72,258	ruitenwisservloeistof	Bijvullen/-laden
2/17/26	72,258	service luchtfilter	Uitvoeren
2/17/26	72,258	service microfilter	Uitvoeren
2/17/26	72,258	service motorolie	Uitvoeren
6/12/25	61,258	BMW/MINI service standaard omvang	Uitvoeren
6/12/25	61,258	controle niveaus	Uitvoeren
6/12/25	61,258	remvloeistof	Vervangen
3/22/24	36,585	batterij	Vervangen
3/22/24	36,585	BMW/MINI service standaard omvang	Uitvoeren
3/22/24	36,585	ruitenwisserrubber achter	Vervangen
3/22/24	36,585	ruitenwisserrubber vooraan	Vervangen
3/22/24	36,585	service microfilter	Uitvoeren
3/22/24	36,585	service motorolie	Uitvoeren