



AUDI A3 SPORTBACK:

Vinnumber:	WAUZZ28V7LA062878	Versionname:	1.6 30 TDi 85kw
First Registrationdate:	26/02/2020	Fiscalpower:	
Expertise Mileage:	160190	Power Kw:	85
Bodytype:		Body colour:	Dark Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2301
Fueltype:	Diesel		
Maintenance:	OK		
Maintenance:	16200.0		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	Tow bar collapsible
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	SD present		

Limited Technical Inspection

Tyres

205/55/16/94 V				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/55 R 16 94 V
Tyre size FR				235/45 R 18 98 V
Tyre size RL				235/45 R 18 98 V
Tyre size RR				235/45 R 18 98 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	1484,49
Engine insulation, Tear, Replace	0,00



Bonnet, Stone chip(s), Acceptable 0,00



Alloy rim RL, Scratch(es), Repair and paint (complete) 133,03



Door RL, Dent(s), Acceptable 0,00



Alloy rim FL, Scratch(es), Repair and paint (complete) 133,03



Door FL, Dent(s), Paintless dent repair 95,47



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete) 434,80



Door FL, Scratch(es), Acceptable 0,00



Outer door handle FL, Scratch(es), Repair and paint (complete) 161,81



Bumper R, Scratch(es), Repair and paint (complete)

296,58



Rubber seal for boot lid, Deformed / Strained, Replace

96,74



Alloy rim FR, Scratch(es), Repair and paint (complete)

133,03



Door FR, Dent(s), Acceptable

0,00



Roof, Scratch(es), Acceptable

0,00

