



## TOYOTA Corolla: 5111-MGF

Vinnumber:	<b>SB1K93BE00E350616</b>	Versionname:	<b>1.8 125H ACTIVE TECH E-CVT berlina con portón</b>
First Registrationdate:	<b>19/04/2023</b>	Fiscalpower:	<b>90kW 5P automática</b>
Expertise Mileage:	<b>164508</b>	Power Kw:	
Bodytype:	<b>Berline</b>	Body colour:	<b>White</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:			
Fueltype:	<b>Hybrid</b>		
Engine functioning:	<b>Yes</b>		
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>No</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>No</b>		

## Options

Number of keys total	<b>2</b>	Central consol F
Number keys remote	<b>2</b>	Luggage cover
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	<b>Autom climate control</b>	

## Tyres

205/55/16/91 V				
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>
Tyre profile depth FL				<b>3.0</b>
Tyre profile depth FR				<b>3.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>205/55 R 16 91 V</b>
Tyre size FR				<b>205/55 R 16 91 V</b>
Tyre size RL				<b>205/55 R 16 91 V</b>
Tyre size RR				<b>205/55 R 16 91 V</b>
Tyre make FL				<b>259</b>
Tyre make FR				<b>259</b>
Tyre make RL				<b>259</b>
Tyre make RR				<b>259</b>

## Assistance equipment

Repair kit	<b>Yes</b>
<b>Boot lid covering R, Scratch(es), Replace</b>	



Interior, Dirty, Cleaning



MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Wing RL, Dent(s), Acceptable



Door FL, Scratch(es), Repair and paint (complete)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Bonnet, Dent(s), Acceptable



Wing RR, Dent(s), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

