MACADAM










Volvo XC40: N813RB

Vinnumber:	**YV1XZEFVKN2711058**	Versionname:	**XC40 Recharge Pure Electric 170kW/70kWh Pro automaat**
First Registrationdate:	**17/12/2021**	Fiscalpower:	
Expertise Mileage:	**151175**	Power Kw:	**170**
Bodytype:		Body colour	**Fusion Red metallic**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**459**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Sun Roof electric	
GPS		Panoramic roof	
Autom climate control		Rear parking sensors	
Radio multimedia		Hook	
		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 50 / 19 / 103 / W / Aluminium	6,6 mm	Goodyear	All season
	Right	235 / 50 / 19 / 103 / W / Aluminium	6,6 mm	Goodyear	All season
Rear	Left	255 / 45 / 19 / 100 / W / Aluminium	5,6 mm	Goodyear	All season
	Right	255 / 45 / 19 / 100 / W / Aluminium	6,4 mm	Goodyear	All season

Assistance equipment

Number of charging cables (rapid charge)	**1**

Interior, Dirty, Chemical cleaning









Bumper F, Scratch(es), Polish




Bonnet, Chemical polution, Repair and paint (complete)





Wing RR, Scratch(es), Repair and paint (complete)




Door RR, Scratch(es), Repair and paint (complete)




Door FR, Scratch(es), Repair and paint (complete)





Outside rear-view mirror housing R, Scratch(es), Polish




Bumper corner RL, Scratch(es), Repair and paint (complete)





Bumper R, Scratch(es), Smart repair




Onderhoudshistorie van: YV1XZEFVKN2711058

ALPHABET

Kenteken	N813RB
Merk Model	Volvo XC40 Recharge Pure Electric 170kW/70kWh Pro automaat
Brandstofsoort	Elektrisch
Datum deel1	12/17/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
6/19/26	139,016	Airco controle
6/19/26	139,016	Airco pomp
6/19/26	139,016	Airco vulling
6/19/26	139,016	Isolatiemeting
6/19/26	139,016	Spanningsvrij
11/28/25	124,078	APK
11/28/25	124,078	Onderhoudsbeurt
11/28/25	124,078	Vervanging band
10/31/24	97,591	Onderhoudsbeurt
10/31/24	97,591	Remvloeistof
10/31/24	97,591	Ruitenwisserblad(en) voorzijde
1/23/24	73,002	Vervanging band
11/10/23	65,912	Elektrische achterklep
11/10/23	65,912	Vervanging band
12/19/22	34,226	Vervanging band