



CITROËN BERLINGO: FY-582-BX

Vinnumber:	VR7EFYHYCMN510533	Versionname:	CITROËN BERLINGO Taille M 650kg BlueHDi 100 S&S BVM Club VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)
First Registrationdate:	24/03/2021	Fiscalpower:	75
Expertise Mileage:	169096	Power Kw:	75
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Rear parking sensors	
Windows electric F		Sliding door right-side	
Steering wheel leather		Rear view camera	
Type of climate control	Manual climate control	Seat cover lining	Lining Other

Tyres

	195/65/15/95 H			
Summer tyres:	Fr.L.	Bridgestone: 30%	Fr.R.	Bridgestone: 45%
	Re.L.	Bridgestone: 45%	Re.R.	Bridgestone: 55%
Tyre profile depth FL	6.1			
Tyre profile depth FR	5.2			
Tyre profile depth RL	5.2			
Tyre profile depth RR	4.7			
Tyre size FL	195/65 R 15 95 H			
Tyre size FR	195/65 R 15 95 H			
Tyre size RL	195/65 R 15 95 H			
Tyre size RR	195/65 R 15 95 H			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	255			
Tyre make FR	255			
Tyre make RL	255			
Tyre make RR	255			


Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Air vent, mid-dashboard, Damaged, Replace



Remote ignition key, Missing, Repair/replace (lump sum)



Seat cover FL, Burned, Replace



Interior, Dirty, Cleaning



Inner door sill FL, Scratch(es), Paint



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)

