



Expertise

Protocol number: 45740168
Order No. / Reference: 26405258
Inspection date: 29 May 2026

Manufacturer: CUPRA

Model: Born 170kW/58kWh

VIN: VSSZZK15PP020820



Vehicle details	
Manufacturer / Type / Model / Equipment	
CUPRA Born 170kW/58kWh	
Vehicle Identification number	VSSZZK15PP020820
Mileage (Read)	56,567 km
First registration	31 Mar 2023
Number of holders	1
Power / Engine displacement	70 kw /
Fuel type / Cylinder	Electric / 0
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Saloon car
Colour / colour code	Quasar Grey Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	322 Tag(e)
Last service on / at	04/2025 at 37,509 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ499127
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	7593 / ASM 00012		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,280 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R19 93T	Winter tyres on Light alloy	Continental	7mm / 7mm
2)	215/50 R19 93T	Winter tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R19 93T	Summer tyres on Light alloy	Bridgestone	3mm / 3mm
2)	215/50 R19 93T	Summer tyres on Light alloy	Bridgestone	3mm / 3mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Airbag for driver and front passenger
- Airbag: Head airbag system, front and rear
- Exterior mirrors: aspherical on driver's side, convex on passenger's side
- Battery warranty 8 years, maximum 160,000 km
- C-pillar with CUPRA design element
- CUPRA Drive Profile
- CUPRA lettering on tailgate
- Black headliner
- Electronic parking brake including auto-hold function
- Electric window regulator with anti-pinch protection and one-touch function
- Transmission: 1-speed automatic
- Rear spoiler in car color
- Interior mirror automatically dimming
- Keyless Go (engine start/stop button)
- Air conditioning: Climatronic with electronic temperature control
- Mode 3 Type 2 charging cable, 16 A
- Lights: Full headlights
- front center armrest
- Fatigue detection
- Emergency call service
- Radio: Radio, navigation and multimedia systems
- Tire pressure monitoring system
- Seat belts - front and rear
- Seats: 3 rear seats, rear seat backrest asymmetrically split and foldable
- Sun visors with illuminated makeup mirror
- Lane departure warning system
- Front bumper in body color
- Front Assist area monitoring system with City Emergency Braking function

Extra equipment

- Paint finish: Metallic
- Package: Pilot M Pack (Adaptive Cruise Control ACC with predictive speed control - CUPRA CONNECT PLUS - prepared for activation of the Online Infotainment service package - High Beam Assistant - Traffic Sign Recognition - Navigation system with 12" color touchscreen - Rearview camera)
- Privacy Glass: Side windows from the 2nd row of seats and rear window are dark tinted.

- Airbag: Passenger airbag deactivation
- Ambient lighting in the front door panel
- Electrically adjustable, folding and heated exterior mirrors
- Exterior mirror housing in Liquid Grey
- third brake light
- CCS charging socket
- CUPRA e-Sound
- CUPRA side skirts in Liquid Grey
- decorative elements
- Electronic Stability Control (ESC)
- Luggage compartment lighting
- Speed limiter
- rear window wiper
- Rear bumper and diffuser in body color
- ISOFIX child seat restraint system, in the 2nd row of seats left and right as well as on the front passenger seat
- Headrests, 2 front
- Headrests, 3 rear
- Steering wheel: CUPRA Supersport multifunction steering wheel in leather with CUPRA mode selector
- Center console with integrated storage compartment and cup holders
- Progressive steering
- Rain sensor
- Wheels: TYPHOON 7.5J x 19" alloy wheels, black/silver, diamond-cut finish
- Seats: CUPRA sports bucket seats in the front
- Seats: Driver's seat with height adjustment
- Sport pedals in aluminum look
- 12V socket in the luggage compartment
- Ultrasonic parking aid front and rear
- Electronic immobilizer
- thermal insulation glazing

- Package: Below Zero Pack (Heated front seats - Heated front windshield washer nozzles)
- Package: Pilot M+ Pack
- Package: Tech L Pack
- Package: Tech M Pack (Illuminated exterior door handle recesses - Car2X function - Kessy Advanced, keyless locking and starting system - Wireless Charger)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Stone chips - No deduction
2	Rear bumper	Rear bumper - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Comments

Wartungshistorie gemäß Auftraggeber Informationen.

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.





Figure 32: Misc.



Wear and tear 2: Rear bumper: Rear bumper - dent(s) - No deduction



Wear and tear 2: Rear bumper: Rear bumper - dent(s) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VSSZZZK15PP020820
Hersteller / Modell: SEAT SEAT Born 170kW/58kWh

Datum	KM-Stand	Beschreibung
17.04.2025	37.509	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst