



RENAULT CLIO: GF-141-KV

Vinnumber:	VF1RJA00469054849	Versionname:	RENAULT CLIO Business TCe 90 -21N VP [5P] bvm
First Registrationdate:	25/03/2022	Fiscalpower:	6-90CH-5cv (bi-corps)
Expertise Mileage:	63071	Power Kw:	66
Bodytype:	Berline	Body colour:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Interior colour:	Grey
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Luggage cover	
GPS big screen color		Rear parking sensors	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	195/55/16/87 V			
Summer tyres:	Fr.L.	Hankook: 40%	Fr.R.	Hankook: 40%
	Re.L.	Continental: 50%	Re.R.	Continental: 60%
Tyre profile depth FL				5.6
Tyre profile depth FR				5.6
Tyre profile depth RL				5.0
Tyre profile depth RR				4.3
Tyre size FL				195/55 R 16 87 V
Tyre size FR				195/55 R 16 87 V
Tyre size RL				195/55 R 16 87 V
Tyre size RR				195/55 R 16 87 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Remote ignition key, Missing, Repair/replace (lump sum)



Door RL, Dent(s), Repair and paint (complete)



Wing RL, Scratch(es), Paint



Roof pillar L, Dent(s), Repair and paint (complete)



Bonnet, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Wing RR, Dent(s), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Paint



Outer door handle FR, Scratch(es), Paint



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Paint



Roof pillar R, Dent(s), Repair and paint (complete)



Boot lid covering R, Scratch(es), Replace



Rear bulkhead lining, Scratch(es), Repair/replace (lump sum)



Bumper R, Scratch(es), Paint



Roof, Dent(s), Repair and paint (complete)



Historique Maintenance

Immatriculation: **GF-141-KV** Date de 1ère immatriculation: **25/03/2022**

Modèle: **Renault CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
09/07/2026	63.046	DEKRA AUTOMOTIVE TRAPPES	Contrôle technique
22/01/2026	58.516	GRAND PARC AUTOMOBILES	LIQUIDE DE FREIN
			BOITIER D ALLUMAGE RPLT
			FILTRE A AIR RPLT
			BALAIS ESSUIE GLACE AV
			BATTERIE RPLT
			RECYCLAGE
			SERENITE
04/12/2024	47.690	CAYCHAC BLANQUEFORT AUTOMOBILES CBA	REVISION ET CLIM
			BALAIS ESSUIE GLACE AV
25/09/2023	27.772	CAYCHAC BLANQUEFORT AUTOMOBILES CBA	BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV
			REVISION ET CLIM