MACADAM










Renault Captur: N254NJ

Vinnumber:	**VF1RJB00167691991**	Versionname:	**Captur 1.0 TCE 67kW Business Zen**
First Registrationdate:	**30/11/2021**	Fiscalpower:	
Expertise Mileage:	**133701**	Power Kw:	**67**
Bodytype:		Body colour	**Blanc Nacré**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Petrol**	Parking lot	**611**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Tow bar removable	
Manual climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 96 / H / Aluminium	5,1 mm	Bridgestone	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	5,5 mm	Bridgestone	Summer
Rear	Left	215 / 60 / 17 / 96 / H / Aluminium	5,9 mm	Michelin	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	5,5 mm	Michelin	Summer

Assistance equipment

Door FL, Scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)




Bonnet, Dent(s), Repair and paint (complete)




Door RR, Dent(s), Repair and paint (complete)




Door FR, Dent(s), Repair and paint (complete)




Boot lid covering R, Scratch(es), Replace




Bumper corner RR, Scratch(es), Repair and paint (complete)




Bumper corner RL, Scratch(es), Repair and paint (complete)




Onderhoudshistorie van: VF1RJB00167691991

ALPHABET

Kenteken	N254NJ
Merk Model	Renault Captur 1.0 TCE 67kW Business Zen
Brandstofsoort	Benzine
Datum deel1	11/30/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
4/30/26	129,756	Onderhoudsbeurt
4/30/26	129,756	Remblokken voorzijde
4/30/26	129,756	Ruitenwisserblad(en) voorzijde
10/6/25	120,974	APK
7/21/25	113,894	Uitlijnen voor en achterwielen
7/17/25	113,891	Bougie
7/17/25	113,891	Onderhoudsbeurt
7/17/25	113,891	Ruitenwisserblad(en) voorzijde
7/17/25	113,892	Vervanging band
2/12/25	0	Accu
2/12/25	100,106	Sleutelbatterij
8/9/24	86,716	Inspuitcomputer
7/15/24	85,260	Accu
7/15/24	85,260	Onderhoudsbeurt
7/15/24	85,260	Remvloeistof
7/15/24	85,260	Sleutelbatterij
7/20/23	58,755	Onderhoudsbeurt
7/20/23	58,755	Sleutelbatterij
7/20/23	58,759	Reparatie band(en)
10/21/22	28,975	Onderhoudsbeurt
7/11/22	20,133	Reparatie band(en)
4/6/22	11,315	Reparatie band(en)