



Polestar 2:				
Vinnumber:	LPSVSEGEKNL082460	Versionname:	POLESTAR POLESTAR 2 Long Range Single Motor 231PK 5d/p AUT(534EGPB0K119)	
First Registrationdate:	18/07/2022	Fiscalpower:		
Expertise Mileage:	101296	Power Kw:	170	
Bodytype:		Body colour	Blue	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	2820	
Fueltype:	Electric			
Maintenance	OK			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Seats electric F L		
Cruise Control		Seats electric F R		
Steering wheel multifunctional		Panoramic roof		
Seats F heated		Luggage cover		
Radio multimedia		Front parking sensors		
Type of headlighting	Headlighting LED	Rear parking sensors		
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar collapsible	
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Type of GPS storage	HD			
Limited Technical Inspection				
Tyres				
Summer tyres:	245/45/19/102 V			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				245/45 R 19 102 V
Tyre size FR				245/45 R 19 102 V
Tyre size RL				245/45 R 19 102 V
Tyre size RR				245/45 R 19 102 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261
Assistance equipment				
Repair kit	Yes	Compressor		Yes
Number of charging cables (normal)	1			
Number of charging cables (rapid charge)	1			
Total cost ex VAT				1233,54
Seat cover FL, Worn, Acceptable				0,00



Floor covering FL, Worn, Acceptable 0,00



Floor covering R, Worn, Acceptable 0,00



Bumper F, Bad repair, Repair and paint (complete) 355,89



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Door RL, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 204,21



Bumper R, Scratch(es), Spot repair 148,33





Boot lid covering R, Scratch(es), Smart repair	116,69
--	--------



Boot carpet, Worn, Acceptable	0,00
-------------------------------	------



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Central pillar R, Scratch(es), Acceptable	0,00
---	------



Alloy rim FR polished, Scratch(es), Acceptable	0,00
--	------

