



## PEUGEOT 508 SW: GL-246-MP

Vinnumber:	<b>VR3FCYHZTNY638414</b>	Versionname:	<b>PEUGEOT 508 SW BlueHdi 130 S&amp;S EAT8 GT VP [5P] bva 8-130CH-7cv (break)</b>
First Registrationdate:	<b>4/01/2023</b>	Fiscalpower:	
Expertise Mileage:	<b>127011</b>	Power Kw:	<b>96</b>
Bodytype:	<b>Break</b>	Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Interior colour:	<b>Black</b>
Fueltype:	<b>Diesel</b>	Type of rims (mounted):	<b>Aluminium</b>
Engine functioning:	<b>Yes</b>	Dashboard color:	<b>Black</b>
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		

## Options

Number of keys total	<b>2</b>	Radio	
Number keys remote	<b>2</b>	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	<b>Lining Other</b>
Steering wheel leather			<b>Lining Leather</b>
Type of climate control	<b>Autom climate control</b>		

## Tyres

<b>235/45/18/98 Y</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 65%</b>	Fr.R.	<b>Bridgestone: 65%</b>
	Re.L.	<b>Michelin: 40%</b>	Re.R.	<b>Michelin: 40%</b>
Tyre profile depth FL				<b>4.0</b>
Tyre profile depth FR				<b>4.0</b>
Tyre profile depth RL				<b>5.6</b>
Tyre profile depth RR				<b>5.6</b>
Tyre size FL				<b>235/45 R 18 98 Y</b>
Tyre size FR				<b>235/45 R 18 98 Y</b>
Tyre size RL				<b>235/45 R 18 98 Y</b>
Tyre size RR				<b>235/45 R 18 98 Y</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>255</b>
Tyre make FR				<b>255</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Seat cover FR, Stain, Cleaning



Interior, Dirty, Chemical cleaning



Seat cover RL, Tear, Replace



Backrest cover RL, Tear, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door lock FL, Strained, Replace



Wing RL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Door FR, Dent(s), Repair and paint (complete)



## Historique Maintenance

Immatriculation: **GL-246-MP**

Date de 1ère immatriculation: **04/01/2023**

Modèle: **Peugeot 508 SW BlueHDi 130 S&S EAT8 GT VP [5P] bva 8-130CH-7cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
10/12/2025	111.678	SIAA	FILTRE CLIM RPLT
	0		REVISION
	0		RECYCLAGE
	0		DIVERS FREIN
	0		DISQUES PLAQUETTES AV RPLT
	0		BALAISSUIE GLACE AV
	0		LIQUIDE DE FREIN
11/04/2025	92.000	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
09/04/2025	82.835	SIAA	RECYCLAGE
	0		REVISION
28/11/2024	66.120	SIAA	BALAISSUIE GLACE AR
18/10/2024	60.817	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
06/09/2024	56.141	SIAA	BALAISSUIE GLACE AV
	0		REVISION
	0		FILTRE A AIR RPLT
	0		FILTRE CLIM RPLT
	0		REVISION
	0		RECYCLAGE
29/01/2024	30.131	SIAA	RECYCLAGE
	0		REVISION