



Renault Captur: N468HG

Vinnumber:	VF1RJB00067975662	Versionname:	Captur 1.3 103kW GPF Intens EDC
First Registrationdate:	15/10/2021	Fiscalpower:	
Expertise Mileage:	172522	Power Kw:	103
Bodytype:		Body colour:	Two-tone Bleu Iron / Noir Etoilé
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	1123
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options


Number of keys total	2	Lining semi-leather
GPS		Sun Roof electric
Autom climate control		Rear parking sensors
Radio multimedia		Tow bar removable

Tyres


Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 96 / H / Aluminium	6,1 mm	Continental	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	6,4 mm	Continental	Summer
Rear	Left	215 / 60 / 17 / 96 / H / Aluminium	6,1 mm	Continental	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	6,7 mm	Continental	Summer

Assistance equipment

Wing RL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bonnet, Stone chip(s), Repair and paint (complete)



Bumper F, Stone chip(s), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Boot lid covering R, Scratch(es), Replace



Bumper corner RL, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Smart repair



Roof, Chemical polution, Repair and paint (complete)



Kenteken	N468HG
Merk Model	Renault Captur 1.3 103kW GPF Intens EDC
Brandstofsoort	Benzine
Datum deel1	15-10-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
26-05-26	171.000	Vervanging band
28-10-25	145.422	Multiriem inclusief geleiderol
28-10-25	145.422	Multiriem inclusief spanner
28-10-25	145.422	Onderhoudsbeurt
28-10-25	145.422	Radiator
28-10-25	145.422	Ruitenwischerblad(en) achterzijde
28-10-25	145.422	Ruitenwischerblad(en) voorzijde
28-10-25	145.422	Sleutelbatterij
20-10-25	144.295	Vervanging band
23-04-25	119.678	APK
23-04-25	119.678	Bougie
23-04-25	119.678	Luchtfilter
23-04-25	119.678	Onderhoudsbeurt
23-04-25	119.678	Remtrommel
23-04-25	119.678	Ruitenwischerblad(en) achterzijde
23-04-25	119.678	Ruitenwischerblad(en) voorzijde
18-06-24	89.254	Onderhoudsbeurt
18-06-24	89.254	Remschijf + blokken voor
18-06-24	89.254	Remvloeistof
18-06-24	89.254	Ruitenwischerblad(en) achterzijde
18-06-24	89.254	Ruitenwischerblad(en) voorzijde
18-06-24	89.254	Sleutelbatterij
06-11-23	65.485	Vervanging band
11-08-23	57.590	Bougie
11-08-23	57.590	Luchtfilter
11-08-23	57.590	Onderhoudsbeurt
11-08-23	57.590	Ruitenwischerblad(en) achterzijde
11-08-23	57.590	Ruitenwischerblad(en) voorzijde
10-10-22	28.357	Onderhoudsbeurt
10-10-22	28.357	Ruitenwischerblad(en) voorzijde