Audi

AUDI Q3 SPORTBACK (F3N)(08.2019->) 45 TFSI E BASE HYBRIDE 180 KW (MOTEUR 1,4 LITRE(S) - 110 KW TFSI) 4 PORTES

VIN: WAUZZZF32N1136521



Description

Registration number 2CCS365	**Registration date** 07/06/2022	**Odometer** 99862 km
Color Gris Nano Métallisé	**Year** 2020	**Upholstery** -
Number of doors 4	**Number of seats** 5	**Generation** -
Engine displacement 1395	**Gearbox type** Automatic	**Engine type** Plug-in Hybrid
Fuel Type Petrol	**Number of gears** 6	**Drivetrain** Front Wheel Drive (FWD)
Max power 180 KW		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Vehicle Equipments

Standard

driver assistance system: emergency assistant with automatic emergency call	multi-media Interface MMI basic plus / MMI radio plus	6 speaker(s)
interior equipment decorative trim inserts accent parts in the instrument panel in glass look black	center armrest front with compartment	airbag driver side/passenger side
airbag passenger side deactivatable	sidebag front	generator 140 A
immobilizer (electronic)	Audi Drive Select	battery 59 Ah
roof edge spoiler	transmission 6-speed - dual-clutch transmission DSG	body: 4-door
comfort automatic air-conditioning 2-zone	auxiliary air-conditioning	radio-remote key
charging cable with industrial plug (16 A / 400 V)	charging cable for public charging pillars (mode 3)	progressive steering
voice-command system	light and rain sensor	charging system alternating current (AC)
electronic stability control (ESC)	wheelbase 2680 mm	Entretien: sans Longlife-Service
interior equipment decorative trim inserts Micro metallic	turn signal lights LED in exterior mirror integrated	gasoline particulate filter (GPF)
parking brake electromechanical	roof liner anthracite	windshield washer jets heated
universal interface Bluetooth	tire repair kit	Type of drive: front-wheel drive
Moteur 1,4 litre(s) - 110 kW (Système : 180 kW) 16V TFSI Hybride (DGEA)	electric motor 85 kW (hybrid drive)	low emissions according to emission standard Euro 6d
Shine package	sound generator (inside)	windshield acoustic glass
windshield heat protection glazing	bumper variant: base	Plug-in hybrid
scuff rails black	acoustic pedestrian protection (external sound)	loading edge protector
radio reception digital (DAB)	exterior mirror vehicle colour	standard seats front
floor mats velours	comfort suspension (Agility Control)	head airbag system (Sideguard)
antilock braking system (ABS)	driver assistance system: lane-change and lane assistant (Side Assist and Lane Assist)	driver assistance system: brake assistant (Audi pre sense front)
driver assistance system: passenger protection system (Audi pre sense basic)	start/stop system	child lock electrically operated
tire puncture indicator		

Optional

parking aid front and rear, optical (APS Plus)	Audi connect (Remote / Control)	Audi connect (web-based services)
Audi connect (Emergency and Assistance System)	Audi Smartphone Interface	rear lid open+close automatic (Hands-Free-Access system)
reversing camera	front camera (multi-functional camera windshield)	instrument cluster digital (virtual cockpit plus)
Disques de frein AR (310 mm x 22 mm)	Disques de frein AV (340 mm x 30 mm)	rear seat backrest split/folding, sliding with center armrest (40:20:40)
rear lights LED	refrigerant R 1234 YF	light alloy rims 7x18 (5-double-arm Design)
multi-media Interface MMI Navigation Plus	driver assistance system: traffic sign detection	metallic paintwork
headlight LED and rear lights LED	exterior mirror aspherical, left	exterior mirror convex, right
exterior mirror electrically adjustable, heated + folding, with automatic dimming and automatic curb-view tilting	exterior mirror with automatic curb-view tilting, right	interior mirror with automatic dimming
seat covers/upholstery: leather / imitation leather mono.pur 550 combination	seat heating front	driver assistance system: start-up assistant (hold-assist)
driver assistance system: automatic distance control (ACC)	steering wheel (leather - 3-spokes) with multiple function plus and shift function	ambient lighting

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	12/10/2026	13/10/2026

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Door / Back Left	Scratched	Acceptable
			
002	Bumper / Back Painted : Yes	Scratched	Painting
	   		

Loose Items

- ☑ Quick charging cable (Type 2, Mode 3)
- ☑ Triangle
- ☑ Rear parcel shelf
- ☑ Spare Key
- ☑ Tyre repair kit complete
- ☑ First aid kit
- ☑ Conformity certificate
- ☑ Safety vest
- ☑ Document holder
- ☑ Registration certificate owner
- ☑ Registration certificate

Main set of tyres

Front Left	CONTINENTAL	235/55/18 Summer	3 mm
Front Right	CONTINENTAL	235/55/18 Summer	3 mm
Back Left	CONTINENTAL	235/55/18 Summer	5 mm
Back Right	CONTINENTAL	235/55/18 Summer	5 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer



Navigation




Spare Tyre




Cable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Vin


Other



Other


Other



Other


Door / Back Left / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.