

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia					
				Policyholder				Opposite party				Opposite party company			
				Operation 2026		Claim number		Code / Agency				Date accident 02/07/2026			
				Expert code		Adjuster code		Policy number				Injured person can recover the VAT			
Date assignment 02/07/2026		Date first survey 09/07/2026		Place MILANO		C/O	Repairs		Photo	Lien in favor of					
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)										Formerly plate					
Lessee / Co-owner										Date of overhaul					
Vehicle (Brand - Model - Version) MERCEDES-BENZ CLASSE A A 250 e EQ-POWER Automatic Business							Plate GD439AR		Vin Chassis W1K1770861J276970		First Registration 26/10/2020				
Usage status NON CONOSCIUTO		Km 87621	Tyres % 70	Color GRIGIO		Type of enamel METALLIZED/DOUBLE			Consistency of damage		Type of Expert's report NOT DEFINITIVE				
Equipment															
Approval code		For commercial vehicles	Carrying Qls 0	Tare, Q 0	Wheelbase	Seats No. 0						Axles 0			
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses									
Damaged items / restoration operations							SR		LA		VE		ME	D.M. S.C.	Costs of spare parts * (VAT excluded)
							Dif	Time	Dif	Time	Dif	Time	Time		
1	A1776701400	Windshield					S		S		S				
1	Codice Ricambio	Kit collante					S		S		S				
1	A17769054009F93	Parcel shelf					S		S		S				
1	A17788054009999	Rear bumper					S		S		S				
1	A00090555049999	Parking sensor of side rear bumper			R		S		S		S				
1	A1777401400	Rear hatch					S		S		S				
1	A1778170000	Rear stem					S		S		S				
1	A1777301400	Rear door			R		M		M		M				
1	A1777301300	Rear door			L		L		L		L				
1	A1776307901	rear mudguard			L		L		L		M				
1	A1776308201	rear mudguard			R		L		L		M				
1	A1777206205	Front door			R		L		L		L				
1	A17788001009999	Front bumper					L		L		L				
2	Codice Ricambio	Ripristino n°2 cerchi lega post.													

New for old value (N)	Remarks Pneum. INV. Kumho 205/55 R17 Vhl sporco. Presenti due cavi di ricarica (mod2-3); verificare dot. di serie.
-----------------------	--