BMW 3 SERIES TOURING

Vehicle information


Brand:	**BMW**	License plate:	**2CFM973**
Gearbox:		Body color:	
Model:	**3 SERIES TOURING**	LEVEL:	**WBA6N31020FN15281**
Fuel type:		Power:	**135 kW**
Version:	**2.0 330E (215KW) TOURING**	First registration	**05/07/2022**
Mileage:	**150812 km**	Number of doors:	

Summary of damages

Interior	1
Roof & other	1

Commercial photos






























Options according to the inspector

GPS	**Yes**

Damages

Bodywork
Damaged -
Acceptable.
Roof & other









Damaged **Interior**
- Acceptable
Interior







Tires

Front Left
Summer
Aluminum
225/50/17/98/Y
Hankook
4.0 mm
Front Right
Summer
Aluminum
225/50/17/98/Y
Hankook
4.0 mm
Left Back
Summer
Aluminum
225/50/17/98/Y
Hankook
6.0 mm
Rear Right
Summer
Aluminum
225/50/17/98/Y
Hankook
6.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**P/A**	Vehicle inspection	**OK**
Vehicle inspection	**05/07/2027**	Interview	**OK**
Interview	**01/07/2027**	Interview	**15000.0**
Repair kit	**P/A**	Number of charging cables (220V)	**2**
Number of charging cables (fast charging)	**1**	Total number of keys	**2**
Charge level	**10**	Factory reset	**Yes, the vehicle has been reset to factory settings.**
Type of maintenance log	**Digital interview**		

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.