

INSPECTION REPORT




End of contract

GENERAL INFO

File	308895
License plate	2BPL344
Vehicle identification number	WAUZZZGY9NA044851
Dossier	2021 208 056
Make	Audi A3 SB 30 TDi 85kW Bus.Ed.
Mileage	76339
First registration	04/02/2022
client availability date	23/03/2026
inspectionDate	30/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
234	Wing Front right // Repair & Painting	N
272	Bumper Front / Trim Right / Replace	N
35	Front Bonnet // Polish	Y
38	Front Bonnet / Insulation / Replace	N
66	Wing Front Left // Polish	Y
72	Side View Mirror Left // Painting	N
84	Door Front Left // Repair & Painting	N
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
150	Rear Bonnet // Smart Repair Small	N
151	Rear Bonnet // Smart Repair Medium	Y
165	Roof // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
321	Wheel Alloy Rear Left // Repair	Y
341	Wheel Alloy Front Right // Repair	N
411	Seat Front Left // Repair	Y
421	Seat Front Right // Repair	Y


Damage Pictures



Door Front Left // Repair & Painting-scratch + dent



Front Bonnet / Insulation / Replace-cracked



Front Bonnet // Polish-Chemical reaction




Roof // Polish-Chemical reaction



Rear Bonnet // Smart Repair Medium-Chemical reaction



Wing Rear Left // Polish-scratch





Bumper Rear // Painting-scratch




Wheel Alloy Rear Left // Repair-scratch



Seat Front Left // Repair-scratch



Door Rear Left // Painting-scratch



Side View Mirror Left // Painting-scratch



Wing Front Left // Polish-scratch



Seat Front Right // Repair-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Wheel Alloy Front Right // Repair-scratch



Door Front Right // Smart Repair Small-scratch




Rear Bonnet // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Bumper Front / Trim Right / Replace-scratch



Bumper Front // Painting-scratch



Wing Front right // Repair & Painting-scratch + dent