MACADAM








Audi A3 (UKL): 2CHB822

Vinnumber:	**WAUZZZGYXPA005978**	Versionname:	**A3 Sportback Attraction 30 1.0TFSi 110pk/cv 5p**
First Registrationdate:	**26/07/2022**	Fiscalpower:	
Expertise Mileage:	**63176**	Power Kw:	**81**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**over 26200 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/16/94 V**			
	Fr.L.	**Bridgestone: 4 mm**	Fr.R.	**Bridgestone: 4 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**205/55 R 16 94 V**
Tyre size FR	**205/55 R 16 94 V**
Tyre size RL	**205/55 R 16 94 V**
Tyre size RR	**205/55 R 16 94 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Backrest cover FL, Damaged, Acceptable




Backrest cover FL, Scratch(es), Acceptable




Backrest cover FR, Scratch(es), Acceptable





Windscreen, Stone chip(s), Acceptable




Bonnet, Stone chip(s), Acceptable








Bumper F, Scratch(es), Acceptable








Wing FL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable






Door RL, Scratch(es), Acceptable




Wing RL, Scratch(es), Acceptable






Outer sill L, Scratch(es), Acceptable




Internal boot lining R, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable






Door RR, Scratch(es), Acceptable




Door FR, Scratch(es), Acceptable




Roof, Dent(s), Acceptable




Onderhoudshistorie van: WAUZZZGYXPA005978

ALPHABET

Kenteken	2CHB822
Merk Model	Audi A3 Sportback Attraction 30 1.0TFSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	7/26/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/28/26	60,487	bougie	Vervangen
7/28/26	60,487	klein materiaal	
7/28/26	60,487	koelwatervloeistof	Bijvullen/-laden
7/28/26	60,487	luchtfilter interieur	Vervangen
7/28/26	60,487	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
7/28/26	60,487	remvloeistof	Vervangen
7/28/26	60,487	ruitenwisservloeistof	Bijvullen/-laden
5/11/26	55,871	batterij	Vervangen
5/11/26	55,871	kleine testrit	Uitvoeren
5/11/26	55,871	klein materiaal	
4/13/26	52,416	klein materiaal	
4/13/26	52,416	ruitenwisserrubber achter	Vervangen
4/13/26	52,416	ruitenwisserrubber vooraan	Vervangen
1/7/25	36,086	batterij	Vervangen
7/24/24	29,221	batterij	Vervangen
7/24/24	29,221	klein materiaal	Uitvoeren
7/24/24	29,221	luchtfilter interieur	Vervangen
7/24/24	29,221	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
7/24/24	29,221	remvloeistof	Vervangen