


Vehicle details

VIN	VWZZZE1Z LP018545	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate		Model	ID.3 58kWh 1st Plus auto 5d	Maintenance mileage	-
Registration date	06/11/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	116 685 km	Engine size	-	Interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	09/07/2026	Inspection loc.	
-----------------	------------	-----------------	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Wireless charger	✗
Rear parcel shelf	✓
Vehicle charger	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 215/50/19 Summer 5.5 mm



Continental 215/50/19 Summer 5.5 mm



Continental 215/50/19 Summer 5.0 mm

Continental 215/50/19 Summer 5.0 mm

Exterior

2



Part	Alloy wheel 19"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

3



Part	Wing
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

4



Part	Door
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

7



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

8



Part	Fuel filler flap
Position	Back right
Damages	Defective
Severity	-
Repair mode	For info

9



Part	Rear windscreen trim
Position	Back right
Damages	Broken
Severity	-
Repair mode	Replace

10



Part	Wing
Position	Back right
Damages	Rusty
Severity	Diameter (mm) > 4
Repair mode	Repair


11



Part	Door
Position	Front right
Damages	Rusty
Severity	Diameter (mm) > 4
Repair mode	Repair

Interior damage

5



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

6



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

Others

1



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info