



Ssangyong Musso: 2BCB058

Vinnnumber:	KPAXA1EESMP140733	Versionname:	
First Registrationdate:	27/09/2021	Fiscalpower:	
Expertise Mileage:	121009	Power Kw:	133
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	4 Wheel-drive		
Fueltype:	Diesel		
Maintenance:	OK		
Maintenance:	Geen melding		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Central consol F:	
Number keys remote:	2	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:		VS with seats R:	
Board Computer:		Type of Tow bar:	Tow bar fixed
Cruise Control:			
Steering wheel multifunctional:			
Steering wheel leather:			
Seats F heated:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	SD present		

Tyres

255/60/18/112 V				
Summer tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL:				7.0
Tyre profile depth FR:				6.0
Tyre profile depth RL:				7.0
Tyre profile depth RR:				6.0
Tyre size FL:				255/60 R 18 112 V
Tyre size FR:				255/60 R 18 112 V
Tyre size RL:				255/60 R 18 112 V
Tyre size RR:				255/60 R 18 112 V
Tyre type FL:				All seasons
Tyre type FR:				All Seasons
Tyre type RL:				All seasons
Tyre type RR:				All Seasons
Tyre make FL:				259
Tyre make FR:				259
Tyre make RL:				259
Tyre make RR:				259

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Seat cover FL, Worn, Acceptable



Backrest cover FL, Scratch(es), Acceptable



Backrest cover FR, Scratch(es), Acceptable



Interior, Damaged, Acceptable



Windscreen, Stone chip(s), Windscreen repair



Door RL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Bodywork, Not original part, Sticker removal

