



CITROËN BERLINGO: FS-062-PQ

Vinnumber:	VR7EFYHYCLN534365	Versionname:	CITROËN BERLINGO M 650kg BlueHDi 100 S&S BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)
First Registrationdate:	10/09/2020	Fiscalpower:	
Expertise Mileage:	69676	Power Kw:	75
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	2	Radio	
Number keys remote	0	Front parking sensors	
GPS big screen color		Rear parking sensors	
Windows electric F		Sliding door right-side	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	195/65/15/91 H			
Summer tyres:	Fr.L.	Michelin: 55%	Fr.R.	Michelin: 55%
	Re.L.	Kumho: 55%	Re.R.	Kumho: 55%
Tyre profile depth FL				4.6
Tyre profile depth FR				4.6
Tyre profile depth RL				4.5
Tyre profile depth RR				4.7
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 91 H
Tyre size RL				195/65 R 15 91 H
Tyre size RR				195/65 R 15 91 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				2482
Tyre make RR				2482

Assistance equipment

Spare wheel	Yes	Runflat	No
-------------	------------	---------	-----------

Remote ignition key, Missing, Repair/replace (lump sum)



Gear shift lever cover, Tear, Replace



Interior, Stain, Cleaning



Seat cover FL, Burned, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RL, Dent(s), Acceptable



Bumper F, Deformed / Strained, Repair and paint (complete)



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Door trim RR, Scratch(es), Replace



Wing FR, Dent(s), Acceptable



Rear floor trunk, Rust, Paint



Bumper R, Deformed / Strained, Replace



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Load compartment roof, Scratch(es), Paint



Bodywork, Glue residues, Remove lettering



Historique Maintenance

Immatriculation: **FS-062-PQ** Date de 1ère immatriculation: **10/09/2020**

Modèle: **Citroen BERLINGO M 650kg BlueHDi 100 S&S BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
18/12/2025	69.658	SARL COLLIN	BATTERIE RPLT
29/10/2025	69.658	SARL COLLIN	MOTEUR RPLT
	0		HUILE BV CTRL
31/10/2024	55.557	SARL COLLIN	CONTRE VISITE CT
04/09/2024	52.995	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
17/01/2024	36.267	SARL COLLIN	REVISION ET CLIM ET AIR ET CARBURANT
	0		LIQUIDE DE FREIN
	0		DISQUES PLAQUETTES AV RPLT
04/10/2022	22.946	EUROMASTER FRANCE	REMPLACEMENT PNEUS HIVER
	0		PERMUTATIONS PNEUS
28/02/2022	14.874	EUROMASTER FRANCE	PERMUTATIONS PNEUS
	0		GARDIENNAGE
13/12/2021	12.447	EUROMASTER FRANCE	REMPLACEMENT PNEUS HIVER
	0		GARDIENNAGE
08/11/2021	11.120	EUROMASTER FRANCE	REPARATION DE ROUE
04/01/2021	331	EUROMASTER FRANCE	REPARATION DE ROUE