



AUDI A4 AVANT

Vinnumber:	WAUZZZF4XMA055645	Versionname:	2.0 30 TDi 100kW S tronic Business Ed
First Registrationdate:	29/03/2021	Fiscalpower:	
Expertise Mileage:	137094	Power Kw:	100
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3728
Fueltype:	Hybrid Diesel		
Maintenance	NOT OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

205/60/16/92 H				
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/60 R 16 92 H
Tyre size FR				205/60 R 16 92 H
Tyre size RL				205/60 R 16 92 H
Tyre size RR				205/60 R 16 92 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				Summer
Tyre type RR				All Seasons
Tyre make FL				264
Tyre make FR				264
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Total cost ex VAT	2995,49
Service, Maintenance, Check	0,00



Seat cover FL, Damaged, Acceptable	0,00
------------------------------------	------



Backrest cover FL, Scratch(es), Smart repair	116,69
--	--------



Bumper F, Scratch(es), Repair and paint (complete)	296,58
--	--------




Bonnet, Chemical pollution, Acceptable	0,00
--	------




Windscreen, Scratch(es), Polish	0,00
---------------------------------	------



Wing RL, Dent(s), Paintless dent repair	95,47
---	-------



Step L, Dent(s) and scratch(es), Repair and paint (complete)	161,81
--	--------



Door FL, Dent(s), Acceptable	0,00
------------------------------	------



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)	427,34
---	--------



Alloy rim FL, Scratch(es), Repair and paint (complete)	133,03
--	--------



Luggage compartment cover, Missing, Replace	767,45
---	--------



Bumper R. Scratch(es), Repair and paint (complete)	296,58
--	--------




Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------



Alloy rim FR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Wing FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------




Alloy rim RR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Wheel cover RR, Missing, Replace	26,28
----------------------------------	-------



Door RR, Dent(s), Acceptable	0,00
------------------------------	------



Roof, Chemical polution, Repair and paint (complete)	674,26
--	--------

