

BMW

1.5 XDRIVE25E PHEV 162KW)

VIN: WBA71AB0605V32805



Description

Registration	Registration date	Odometer
	03/05/2022	77271 km
Color	Year	Upholstery
MINERALGRAU METALLIC	2020	-
Number of doors	Number of seats	Generation
5	5	-
Engine displacement	Gearbox type	Engine type
1499	Automatic	Plug-in Hybrid
Fuel Type	Number of gears	Max power
Petrol	6	162 KW

Vehicle Equipments

Standard

armrest front	Advantage	airbag driver side/passenger side
sidebag front	immobilizer	driver assistance system: brake assistant (Audi pre sense front)
automatic transmission - with Steptronic (6-speed)	body: 5-door	Parts catalogue facelift
liftgate control automatic	automatic air-conditioning system 2-zone with automatic recirculation control	AUX-IN interface (AUX-IN)
dynamic stability control (DSC)	tire pressure control system	radio reception digital (DAB)
power steering Servotronic	theft protection for wheels (rim locks)	rear seat backrest split/folding (40:20:40)
wheelbase 2670 mm	Entretien: Véhicule avec Intervalle de vidange d'huile 30000 Km / 24 mois	windshield wiper with rain sensor
gasoline particulate filter (GPF)	parking brake electromechanical	windshield washer jets heated
Type of drive: all-wheel drive	Type of drive: xDrive (all-wheel drive)	engine 1,5 liter - 92 kW hybrid (B38)
electric motor 70 kW (hybrid drive)	multiple function for steering wheel	trip computer
Equipment package: ConnectedDrive Services	Storage package	cargo space floor folding
cargo space floor variable	tire 225/50 R18 ..V	acoustic pedestrian protection (external sound)
cruise control with brake function	Isofix mounts for child seat at rear seat	floor mats velours
head airbag system rear	head airbag system front	driver assistance system: Active Guard (brake assistant)
driver assistance system: collision warning system with brake function	driver assistance system: Performance Control	Service system: intelligent emergency call incl. TeleServices
Service system: Connected eDrive Services	Service system: Remote Services	Blue & Me (Bluetooth with voice control, USB port, MP3)
Steering AV European market (EU specific)	central locking system with remote control	heat protection glazing tinted
steering wheel (sport/leather)		

Optional

head-up display	airbag passenger side deactivatable	anti-theft warning system with intrusion protection
lumbar support seat front left and right, electrically adjustable	roof rails black	reversing camera
active hood	interior equipment interior trim strips Oxide Silver, dark matte	refrigerant R 1234 YF
Light-alloy rims	tire repair kit	model variant CO2 scope (code 1CB)
low emissions according to emission standard Euro 6d	mirror package	Parkpilot system front and rear
driver assistance system: parking assistant (Active Park Assist)	metallic paintwork	headlight LED
front fog lights LED	interior mirror with automatic dimming	side/rear-view mirrors with automatic dimming
seat covers/upholstery: cloth	seat heating front	navigation system: Navigation plus (USB)
Service system: Apple CarPlay information (preparation)	Service system: ConnectedDrive Services	

Active warning lights

Brake system indicator

Statement details

Inspection loc
PARC HÖDLMAYR TONGEREN

Statement date
30/07/2026

Inspection approval date
03/08/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Brake system indicator	Defective	Check
			
002	Personal Data / -	None	Cleaning
			
003	Interior complete / -	Stained	Cleaning
			

004	Safety switch for central locking system / Interior Front Left	Defective	Refit
 			
005	Door / Front Left ¹	Dent	Smart repair
  			
006	Door / Back Left ²	Dent	Smart repair
   			
007	Door sill / Interior Back Left ³	Scratched	Painting
   			
008	Door panel / Interior Back Left ⁴	Dent	Acceptable
			
009	Rim / Front Left Material : Aluminium alloy / Rim/Tyre diameter : 17" / Surface : Painted	Scratched	Repair
  			
010	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 17" / Surface : Painted	Scratched	Repair



011 Bumper grille / Front
Painted : No

Scratched

Repair



012 Spoiler / Back
Painted : Yes

Dent

Replace



013 Bumper / Back
Painted : No

Dent

Replace



014 Reflector / Back Right

Broken

Replace




015 Bumper / Back
Painted : Yes

Dent

Repair





016	Rim / Back Right	Scratched	Repair
	Material : Aluminium alloy / Rim/Tyre diameter : 17" / Surface : Painted		




017	Door panel / Back Right	Dent	Acceptable
-----	-------------------------	------	------------



018	Roof / -	Scratched	Acceptable
-----	----------	-----------	------------



019	Wing extension moulding / Front Right ⁵	Dirty	Acceptable
	Painted : No		



¹ X2
² X3
³ X4
⁴ X2
⁵ Ovb

Loose Items

- ☒ Rear parcel shelf
- ☒ Tyre repair kit complete
- ☐ Document holder
- ☒ Registration certificate owner
- ☐ Toolkit
- ☐ Jack handle crank
- ☒ Slow charging cable (Type 2, Mode 2)
- ☐ Charging cable bag
- ☒ Spare Key
- ☐ Service book
- ☐ Towing hook
- ☐ Cargo net
- ☐ Remote key
- ☐ Security Kit
- ☒ Triangle
- ☐ Warranty booklet
- ☐ Hook /Hicth ball
- ☐ Card key
- ☐ Locking wheel nuts key
- ☒ Conformity certificate
- ☐ Spare wheel tyre
- ☐ Quick charging cable (Type 2, Mode 3)
- ☒ Safety vest
- ☐ Remote control
- ☐ Compressor tyre repair kit
- ☒ First aid kit
- ☐ User manual
- ☐ Jack
- ☐ Load cover
- ☐ Refill tyre repair kit
- ☒ Registration certificate
- ☐ Satellite navigation
- ☐ In-car tools
- ☐ Locking wheel nut

Main set of tyres

Front Left	MICHELIN	225 / 55 / 17 / Winter	6 mm
Front Right	MICHELIN	225 / 55 / 17 / Winter	6 mm
Back Left	MICHELIN	225 / 55 / 17 / Winter	7 mm
Back Right	MICHELIN	225 / 55 / 17 / Winter	7 mm

Comments

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat




Front passenger compartment



Front right



Odometer



Navigation




Spare Tyre




Cable




Vin




Other



Other




Other



Other




Other




Brake system indicator / Defective



Brake system indicator / Defective



Personal Data / - / None



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained




Safety switch for central locking system / Interior Front Left / Defective




Safety switch for central locking system / Interior Front Left / Defective



Door / Front Left / Dent



Door / Front Left / Dent



Door / Front Left / Dent




Door / Back Left / Dent



Door / Back Left / Dent



Door / Back Left / Dent



Door / Back Left / Dent



Door sill / Interior Back Left / Scratched



Door sill / Interior Back Left / Scratched



Door sill / Interior Back Left / Scratched



Door sill / Interior Back Left / Scratched



Door panel / Interior Back Left / Dent



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Bumper grille / Front / Scratched



Bumper grille / Front / Scratched



Bumper grille / Front / Scratched



Spoiler / Back / Dent



Spoiler / Back / Dent



Spoiler / Back / Dent



Spoiler / Back / Dent



Spoiler / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Reflector / Back Right / Broken



Reflector / Back Right / Broken



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Rim / Back Right / Scratched



Rim / Back Right / Scratched



Rim / Back Right / Scratched



Door panel / Back Right / Dent



Roof / - / Scratched



Roof / - / Scratched



Roof / - / Scratched



Wing extension moulding / Front Right / Dirty



Wing extension moulding / Front Right / Dirty