



BMW 1 Reeks (UKL): 2EDU885

Vinnumber:	WBA7K110307M62117	Versionname:	116i (F40) 1.5i 109pk/cv 5p
First Registrationdate:	8/09/2023	Fiscalpower:	
Expertise Mileage:	55291	Power Kw:	80
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	NOT OK		
Maintenance	uitvoeren		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/55/16/91 V				
Summer tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 3 mm
Tyre profile depth FL	4.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	3.0			
Tyre size FL	205/55 R 16 91 V			
Tyre size FR	205/55 R 16 91 V			
Tyre size RL	205/55 R 16 91 V			
Tyre size RR	205/55 R 16 91 V			
Tyre type FL	All seasons			
Tyre type FR	All Seasons			
Tyre type RL	All seasons			
Tyre type RR	All Seasons			
Tyre make FL	2480			
Tyre make FR	2480			
Tyre make RL	2480			
Tyre make RR	2480			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Service, Maintenance, Check			



Instrument panel, complete, Not functioning (well), Check



Bumper F, Scratch(es), Spot repair



Bumper F, Scratch(es), Acceptable



Bumper moulding F, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Outer sill L, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable




Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Dent(s), Acceptable



Door RR, Repaired, Check



Bodywork, Paint measurement, Check

