


2-FLP-538

2-FLP-538 · ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 -Clipper - leather seats · 22 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FLP-538	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF0PXXGCHPRG13360
Model	Focus	Cylinder Capacity	999 ^{cm3}
Model Versions	ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 - Clipper - leather seats	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	11-06-2024
		Odometer	60.521 ^{Km}
Body Type	5 door hatchback	Numer Of Keys	2
Color	Black	Interior	Black
Paint Type	Metallic	Number Headrests	5
Production Year	2024		
KW	114		

Images





Accessories

ABS	Electrically adjustable driver's seat
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Front & rear parking sensors
Audio System	Leather steering wheel
Automatic air conditioning	Navigation system
Bluetooth car kit	Rear view camera
Central door locking	Roller cover / parcel shelf
Centre armrest	Seat heating
Cruise control	Steering wheel multifunction
Electric rear windows	Steeringwheel – Heated
Electric windows front	Windscreen – Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Rear Left	5 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Front Right	2 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Rear Right	5 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Spare Tire Type	Compressor					

Damages



Damage Part
Fender – Rear Left



Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Frontdoor – Left



Damage Type
Small scratch(es)

Repair Type
Touch-up / Polish

Acceptable
No



Damage Part
Hood



Damage Type
Stonechipping

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Bumper - Front

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Alloy - Right Front

Damage Type
Damaged

Repair Type
Rim repair

Acceptable
No



Damage Part
Frontdoor - Right

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part

Skirt - Right



Damage Type

Dent(s) & Scratch(es)

Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Reardoor - Right



Damage Type

Dent(s)

Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Alloy - Right Rear



Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part
Bumper - Rear



Damage Type
small dents / small scratches



Repair Type
Panelbeating & Spray

Acceptable
No



Damage Part
Tailgate



Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No