


2-FAX-960


2-FAX-960 · 116iA Business Edition · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FAX-960	Fuel Type	Gasoline
Manufacturer	BMW	VIN	WBA7K110707P11437
Model	1-serie	Cylinder Capacity	1.499 ^{cm3}
Model Versions	116iA Business Edition	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	11-03-2024
Color	Blue	Odometer	81.132 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	80	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Leather steering wheel

Navigation system

Rear parking sensors

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior

Adequate

Maintenance Remarks Olie verversen over 14000 km

Condition interior

Adequate

Previous Repairs

Unknown

Last Maintenance Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Hankook	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Rear Left	4 ^{mm}	Bridgestone	205 ^{mm}	55 ^{mm}	16 ^{inch}	Summer
Front Right	4 ^{mm}	Hankook	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Rear Right	4 ^{mm}	Bridgestone	205 ^{mm}	55 ^{mm}	16 ^{inch}	Summer
Spare Tire Type	None					

Damages




Damage Part

Reardoor – Right



Damage Type

Stains & dirt



Repair Type

Cleaning

Acceptable

No



Damage Part

Frontdoor – Right

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Reardoor – Right

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part
Alloy – Right Front



Damage Type
Damaged

Repair Type	Acceptable
Rim repair	No



Damage Part
Bumper – Front




Damage Type
Scratch(es)

Repair Type	Acceptable
Spray	No




Damage Part
Frontdoor – Left



Damage Type
Door-edge chipped

Repair Type	Acceptable
Acceptable	Yes



Damage Part

Rear seat

Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No