



### Volkswagen ID.3: R401FJ

Vinnnumber:	<b>VWZZZE1ZNP038930</b>	Versionname:	<b>ID.3 107kW / 62kWH Pro automaat</b>
First Registrationdate:	<b>29/08/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>81220</b>	Power Kw:	<b>107</b>
Bodytype:		Body colour:	<b>Mangan Grey metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>721</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

### Options

Number of keys total	<b>2</b>	Rear parking sensors
GPS		
Autom climate control		
Radio multimedia		

### Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 18 / 95 / T / Aluminium	3,0 mm	Bridgestone	Summer
	Right	215 / 55 / 18 / 95 / T / Aluminium	4,0 mm	Bridgestone	Summer
Rear	Left	215 / 55 / 18 / 95 / T / Aluminium	3,3 mm	Continental	Summer
	Right	215 / 55 / 18 / 95 / T / Aluminium	2,5 mm	Continental	Summer

### Assistance equipment

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>1</b>

Floor mat(s), Missing, Replace



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)





Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s), Paintless dent repair



Door FR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Dent(s), Repair and paint (complete)



<b>Kenteken</b>	R401FJ
<b>Merk Model</b>	Volkswagen ID.3 107kW / 62kWH Pro automatisch
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	29-08-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
04-06-25	54.535	Airo vulling
04-06-25	54.535	Remblokken achterzijde
04-06-25	54.535	Remblokken voorzijde
25-10-24	40.546	Onderhoudsbeurt
25-10-24	40.546	Remvloeistof
25-10-24	40.546	Sleutelbatterij
13-02-24	29.518	Vervanging band