



Peugeot 208: K717TD

Vinnumber:	VR3UHZKXZLT098151	Versionname:	e-208 50kWh 100kW Active automaat
First Registrationdate:	26/02/2021	Fiscalpower:	
Expertise Mileage:	39793	Power Kw:	100
Bodytype:		Body colour	Blanc Banquise standaardlak
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Steel
Fueltype:	Electric	Parking lot	574
Number of seats	5		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	3	Rear parking sensors
GPS		Rear view camera
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 91 / V / Steel	6,0 mm	Michelin	Winter
	Right	195 / 55 / 16 / 91 / V / Steel	5,4 mm	Michelin	Winter
Rear	Left	195 / 55 / 16 / 91 / V / Steel	5,2 mm	Michelin	Winter
	Right	195 / 55 / 16 / 91 / V / Steel	4,6 mm	Michelin	Winter

Assistance equipment

Number of charging cables (rapid charge)	1
Wheel arch cover FL, Scratch(es), Replace	



Wing FL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Wheel arch cover FR, Scratch(es), Replace



Wing FR, Dent(s), Repair and paint (complete)



Bodywork, Chemical polution, Polish



Kenteken	K717TD
Merk Model	Peugeot e-208 50kWh 100kW Active automaat
Brandstofsoort	Elektrisch
Datum deel1	26-02-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
23-09-25	36.099	Onderhoudsbeurt
23-09-25	36.099	Remvloeistof
23-09-25	36.099	Vervanging band
28-04-25	33.323	Ruitenwischerblad(en) voorzijde
14-02-25	32.804	APK
14-02-25	32.804	Boordcomputer
14-02-25	32.804	Tractie batterij lader
20-07-23	18.558	Onderhoudsbeurt
20-07-23	18.558	Remvloeistof
21-07-22	9.319	Onderhoudsbeurt