



Expertise

Protocol number: 46387082
Order No. / Reference: 26520458
Inspection date: 7 Jul 2026

Manufacturer: Volvo

Model: V60 Cross Country B4 D AWD Geartronic Pro

VIN: YV1ZZK5VCN2094424



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volvo V60 Cross Country B4 D AWD Geartronic Pro	
Vehicle Identification number	YV1ZZK5VCN2094424
Mileage (Read)	82,697 km
First registration	5 May 2022
Number of holders	1
Power / Engine displacement	145 kw / 1,969 ccm
Fuel type / Cylinder	Hybrid Diesel / E / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Denim-Blue Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	0 Tag(e)
Last service on / at	06/2025 at 64,897 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GF858588
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	9101 / BTG 00024		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,360 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R18 99V	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	215/55 R18 99V	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R18 99V	Winter tyres on Light alloy	Semperit	5mm / 5mm
2)	215/55 R18 99V	Winter tyres on Light alloy	Semperit	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/60 R19 94M	Summer tyres on Steel	Sonstige	4 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- ABS - Anti-lock Braking System
- Driver and passenger side airbags with two-stage deployment system
- Electrically adjustable exterior mirrors
- Outdoor temperature display
- Hill Descent Control (HDC)
- Hill Start Assist (HSA)
- LED turn signals integrated into the exterior mirrors
- third brake light
- CleanZone air quality system
- Connected Safety
- Roof edge spoiler
- Digital instrumentation with a 12.3" full-graphic display (31.2 cm diagonal, high resolution)
- Inserts: Drift Wood
- Aluminum door sill plates with Volvo lettering at the front
- Electronic differential lock
- Electric windows front and rear
- Automatic emergency braking
- Cruise control system with variable speed limiter
- Front seat belt height adjustment
- rear window wiper
- Interior lighting
- Intelligent driver information system
- Keyless Drive (electronic access system)
- Automatic air conditioning
- Rear headrests foldable, electrically
- Stainless steel loading sill protector in the luggage compartment
- LED headlights "Thor's Hammer"
- Steering wheel: Multifunction buttons on the steering wheel
- Illuminated makeup mirror for driver and front passenger
- Front center armrest with integrated storage compartment and cup holders
- Oncoming Lane Mitigation
- Electric parking brake
- Particulate filter: Soot particle filter for diesel engines
- Radio accessories: Apple CarPlay and Android Auto
- Radio accessories: Two USB-C ports on the back of the center console
- Road Sign Information (RSI)
- Wheels: 18" 5-spoke CROSS COUNTRY alloy wheels, diamond cut/ graphite look
- Safety braking system with disc brakes all around (internally ventilated)
- Seats: Driver and front passenger seats are height-adjustable (electrically)
- Front seat heating
- Power socket
- Lashing eyes in the luggage compartment (foldable)
- Preparation for Trailer Stability Assist (TSA)
- Front passenger airbag can be deactivated
- All-wheel drive (AWD) with Instant Traction
- Electrically folding exterior mirrors
- Heated exterior mirrors and rear window (automatic)
- Attachment system for carrier bags in the luggage compartment
- fog sensor
- On-board computer with vehicle control functions
- City Safety
- Colored glazing
- Cross Country
- Aluminum roof rails (integrated)
- Drive Mode
- Driver Alert - Attention Warning
- Rear parking assist
- Electronic Stability Control (ESC)
- Chassis: Cross County chassis
- Window surround in high-gloss black
- Luggage compartment partition net
- Transmission: 8-speed Geartronic
- Automatic tailgate (electric)
- Interior and exterior mirrors with automatic dimming function
- ISOFIX anchors for the outer rear seats
- Child safety lock (manual, rear doors)
- Headrests (5) front and rear,
- Charging box under the cargo floor
- Cargo area roller blind
- Lane Keeping Aid (LKA) - Active lane keeping assistant
- Steering wheel adjustable for height and reach
- Steering wheel heating
- Rear center armrest (foldable) with cup holders
- Sensus navigation system
- Emergency brake lights
- Package: Seat Comfort Package
- Parking ticket holder
- Radio: Sensus Connect infotainment system
- Radio accessories: Digital radio reception (DAB+)
- Rain sensor
- Road Edge Detection
- Run-off Road Protection
- Wheels: Tire pressure monitoring system (passive)
- Speed-sensitive power steering
- Seat belts
- Safety steering column (adaptive)
- Seats: Rear seats in a 40/60 split or fully foldable with pass-through function
- Start/Stop technology
- Fuel filler neck with misfuelling protection
- Volvo On Call with WiFi hotspot
- Immobiliser



- WHIPS whiplash protection system

- Central locking system with two remote controls and integrated emergency keys

Extra equipment

- Alarm system (with motion/tilt sensor, security locking and private locking (separate trunk locking))
- Paint finish: Metallic paint
- Package: Lighting Package (LED fog lights - headlight cleaning system - full LED headlights "Thor's Hammer" Active High Beam with extended high beam, dynamic cornering lights, intelligent high beam assist with adaptive headlight range control and integrated LED daytime running lights - ambient lighting, extended interior lighting: multi-colored ambient lighting front/rear, exit lights front/rear, illuminated door pockets and door handles front/rear, illuminated cup holders front, footwell lighting rear, reading lights rear, work light on the tailgate.)
- Park Assist Pilot (Intelligent Parking Assistant) in conjunction with the Parking Assistance Package (including front and rear parking sensors, parking assistant for parallel and perpendicular parking spaces (left and right) as well as exiting parallel parking spaces. Steering is controlled by the assistant, acceleration and braking are controlled by the driver. The parking space must be at least 1.2 times the length of the vehicle.)
- Radio: Audio system High Performance Sound Pro by Harman/Kardon (600 watts of power - 14 speakers - Fresh Air Subwoofer - Dirac Unison sound optimization)
- Auxiliary heater with timer (fuel-operated) (remote activation via Volvo On Call app possible)
- Towbar (semi-electric)
- CROSS COUNTRY side skirts (factory preparation design package CROSS COUNTRY)
- Package: Parking Assistance Package (front and rear parking aid - reversing camera)
- Package: Xenium Package (Automatic climate control with 4-zone temperature regulation - Panoramic glass sunroof with tilt function and integrated, continuously adjustable electric sunshade - High Performance Sound Pro audio system by Harman/Kardon - 600 watts of power - 14 speakers - Fresh Air subwoofer - Dirac Unison sound optimization - Enhanced air quality system with fine dust filter - Leather-look dashboard with contrast stitching)
- Parking camera with 360° surround view in conjunction with parking assistance package
- Pilot Assist (Adaptive cruise control with distance warning - Lane keeping assist up to 130 km/h - Curve Speed Assist (CSA) - Adjustment of vehicle speed before curves based on map data)
- Upholstery: Tailored Wool sports seats (incl. rear center armrest - insert: Linear Lime)
- Wheels: Spare wheel (steel rim) (incl. jack and tools)
- Side and rear windows tinted (from the B-pillar back)
- Rear seat heating (outer rear seats)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Steering system	Steering wheel - Scratched - Smart repair
2	Wing mirror - right side	Cap - Scratch(es) - Smart repair
3	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
4	Misc.	Inspection / maintenance - Expired - Perform



Wear and tear

No.	Component group	Description
1	Interior	Interior - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction
5	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig und eingeschränkt möglich.
- Mehrkosten möglich .
- Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.




Figure 36: Misc.



Figure 37: Misc.





Figure 38: Misc.



Damage 1: Steering system: Steering wheel - Scratched - Smart repair



Damage 1: Steering system: Steering wheel - Scratched - Smart repair



Damage 1: Steering system: Steering wheel - Scratched - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair




Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 3: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 4: Misc.: Inspection / maintenance - Expired - Perform

Wartungshistorie

(gemäß Auftraggeber Informationen)



Fahrgestellnummer: YV1ZZK5VCN2094424

Hersteller / Modell: VOLVO VOLVO V60 Cross Country B4 D AWD Geartronic Pro

Datum	KM-Stand	Beschreibung
25.06.2025	64.897	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
12.05.2025	61.680	HU + AU
05.06.2024	42.772	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges
30.05.2023	17.085	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges