



BMW X3 (KKL): 2BVE052

Vinnumber:	WBA15BZ050N139044	Versionname:	X3 (G01) 2.0d xDrive 20d 163pk/cv 5p Aut.
First Registrationdate:	4/04/2022	Fiscalpower:	
Expertise Mileage:	127906	Power Kw:	120
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Diesel		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	245/50/19/105 W			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				245/50 R 19 105 W
Tyre size FR				245/50 R 19 105 W
Tyre size RL				245/50 R 19 105 W
Tyre size RR				245/50 R 19 105 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Backrest cover FR, Worn, Acceptable



Seat cover FL, Worn, Acceptable



Bumper F, Scratch(es), Spot repair



Alloy rim RL polished, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Door trim RR, Scratch(es), Replace



Door trim FR, Scratch(es), Replace



Bodywork, Paint measurement, Acceptable



Kenteken	2BVE052
Merk Model	BMW X3 (G01) 2.0d xDrive 20d 163pk/cv 5p Aut.
Brandstofsoort	Diesel
Datum deel1	4/4/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
8/4/25	105,905	diagnose	Uitvoeren
8/4/25	105,905	foutencodes uitlezen	Uitvoeren
8/4/25	105,905	klein materiaal	
8/4/25	105,905	versnellingsbakolie	Bijvullen/-laden
8/1/25	105,906	batterij	Vervangen
8/1/25	105,906	BMW/MINI service standaard omvang	Uitvoeren
8/1/25	105,906	BMW/MINI service voertuig-check	Uitvoeren
8/1/25	105,906	klein materiaal	
8/1/25	105,906	ruitenwisservloeistof	Bijvullen/-laden
8/1/25	105,906	service luchtfilter	Uitvoeren
8/1/25	105,906	service microfilter	Uitvoeren
8/1/25	105,906	service motorolie	Uitvoeren
11/20/24	83,595	BMW/MINI service standaard omvang	Uitvoeren
11/20/24	83,595	controle niveaus	Uitvoeren
11/20/24	83,595	klein materiaal	
11/20/24	83,595	remblokken achter	Vervangen
10/4/24	79,134	BMW/MINI service standaard omvang	Uitvoeren
10/4/24	79,134	klein materiaal	Uitvoeren
10/4/24	79,134	remvloeistof	Vervangen
10/4/24	79,134	service brandstoffilter	Uitvoeren
10/4/24	79,134	service microfilter	Uitvoeren
10/4/24	79,134	service motorolie	Uitvoeren
10/11/23	51,644	batterij	Vervangen
10/11/23	51,644	BMW/MINI service standaard omvang	Uitvoeren
10/11/23	51,644	BMW/MINI service voertuig-check	Uitvoeren
10/11/23	51,644	klein materiaal	Uitvoeren
10/11/23	51,644	ruitenwisserrubber achter	Vervangen
10/11/23	51,644	ruitenwisserrubber vooraan	Vervangen
10/11/23	51,644	service luchtfilter	Uitvoeren
10/11/23	51,644	service microfilter	Uitvoeren
10/11/23	51,644	service motorolie	Uitvoeren
1/4/23	25,701	batterij	Vervangen
1/4/23	25,701	BMW/MINI service standaard omvang	Uitvoeren
1/4/23	25,701	service microfilter	Uitvoeren
1/4/23	25,701	service motorolie	Uitvoeren