Technician
Marcel Peeters

2-FKC-951

2-FKC-951 · COMBI L2H12.0dCi 150 DCT N-CONNECTA · 4 November 2026 · Zaventem Brussel

Specifications

License Plate Number	2-FKC-951
Manufacturer	NISSAN
Model	Primastar
Model Versions	COMBI L2H12.0dCi 150 DCT N-CONNECTA
Body Type	VAN
Color	Black
Paint Type	Metallic
Production Year	2024
KW	110
Fuel Type	Diesel

VIN	VNVJ4000573222271
Cylinder Capacity	1.997 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	29-05-2024
First Registration	29-05-2024
Odometer	92.000 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	9

Images
































Accessories

ABS	Leather steering wheel
Airbags	Manual air conditioning
Audio System	Navigation system
Bluetooth car kit	Rear parking sensors
Central door locking	Rear view camera
Cruise control	Roller cover / parcel shelf
Electric windows front	Steering wheel multifunction
Electrically adjustable exterior mirrors	Tow bar
Fog lights	

Condition

Condition exterior	Adequate	Last maintenance odometer	80.695
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance	24-04-2026		

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Rear Left	4 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Front Right	3 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Rear Right	4 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Spare Tire Type	Fully Fledged					
Spare Tire Profile	8 mm					

Damages





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Cargodoor – Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Door-edge chipped	Touch-up	No




Damage Part	Damage Type	Repair Type	Acceptable
Mirror - leftside	Broken	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Small dent(s)	Restyle	No





Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Scratch(es)	Plastic Repair	No





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Mirror - Rightside	Scratch(es)	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Door-edge chipped	Touch-up	No




Damage Part	Damage Type	Repair Type	Acceptable
Skirt – Right	Scratch(es)	Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Fender – Rear Right	Dent(s)	Stootlijst	Replace	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Cargodoor – Right	Scratch(es)	Stootlijst	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Cargodoor – Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Hoekje	Replace	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Broken	3e remlicht	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Dent(s) & Scratch(es)	Panelbeating & Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Roof	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No