



PEUGEOT 308 SW: 1

Vinnumber:	VF3LCYHZRLS158323	Versionname:	1.5 BlueHDi 130 S&S EAT8 Active
First Registrationdate:	28/07/2020	Fiscalpower:	
Expertise Mileage:	167835	Power Kw:	96
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2410
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Panoramic roof	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/45/17/92 H				
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Firestone: 5 mm	Re.R.	Firestone: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/45 R 17 92 H
Tyre size FR				225/45 R 17 92 H
Tyre size RL				225/45 R 17 92 H
Tyre size RR				225/45 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				258
Tyre make FR				258
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	5882,90
Instrument panel, complete, Scratch(es), Replace	906,85



Door panel RR, Broken, Replace

520,37



Wing RL, Dent(s), Acceptable

0,00



Step L, Scratch(es), Repair and paint (complete)

161,81



Door FL, Dent(s) and scratch(es), Acceptable

0,00



Boot carpet, Damaged, Replace

582,28



Shutter / cover R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Repair and paint (complete)

296,58



Rear light R, Scratch(es), Replace

346,55



Tailgate / Boot, Scratch(es), Repair and paint (complete)

422,44



Bumper moulding R, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

204,21



Door FR, Scratch(es), Acceptable

0,00



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

431,58



Step R, Scratch(es), Repair and paint (complete)

161,81



Roof pillar R, Dent(s) and scratch(es), Repair and paint (complete)

308,32



Aerial, Missing, Replace

27,40



Roof, Dent(s), Acceptable

0,00



Panoramic roof, Scratch(es), Replace

1512,70

