



BMW X1

Vinnumber:	WBA31AC0105T91039	Versionname:	
First Registrationdate:	9/06/2021	Fiscalpower:	
Expertise Mileage:	110633	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3825
Fueltype:	Diesel		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

225/55/17/101 Y				
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 101 Y
Tyre size FR				225/55 R 17 101 Y
Tyre size RL				225/55 R 17 101 Y
Tyre size RR				225/55 R 17 101 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	837,84
Door RL, Scratch(es), Repair and paint (complete)	445,79



Bump (es), Repair and paint (complete)

296,58



Tailgate / Boot, Scratch(es), Acceptable

0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00



Door FR, Dent(s), Paintless dent repair

95,47

