BMW

1.5 XDRIVE25E PHEV 162KW)

VIN: WBA71AB0505V46016



Description

Registration number 1FYZ516	**First registration date** 15/07/2022	**Odometer** 153588 km
Color BLACK SAPPHIRE METALLIC	**Model year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 1499	**Gearbox type** Automatic	**Engine type** Plug-in Hybrid
Number of gears 6	**Max power** 162 KW	

Vehicle Equipments

Alloy wheel rims	Climate control	Cruise control
Hydraulic tail board	Rear sensors	Front sensors
Towing	Automatic headlights	Heated seats
Electrically adjustable seats	Sliding roof	SATNAV

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 27/10/2026	**Inspection approval date** 28/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Roof / - [1]	Scratched	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



002	Door sill / Back Left	Scratched	Acceptable



003	Door panel / Back Left	Dent	Acceptable




004	Interior tailgate lining / Upper Front	Scratched	Replace




005	Interior tailgate lining / -	Scratched	Replace






006	Fire extinguisher / -	Non Compliant	Replace




007	Bonnet / -	Paint etching	Repair


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

008	Interior complete / -	Stained	Cleaning





009	Bumper / Back [2] Painted : Yes	Dent	Repair





010	Door / Back Right	Dent	Repair






011	Wing / Front Right	Scratched	Acceptable




012	Rim / Front Right Rim/Tyre diameter : 17 "	Scratched	Repair




013	Door / Front Right	Dent	Smart repair

014	Wing / Front Left	Dent	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



[1] Polissage

[2] Enfoncement avec éclat de la peinture

Loose Items

- Slow charging cable (Type 2, Mode 2)
- Quick charging cable (Type 2, Mode 3)
- Conformity certificate
- Registration certificate
- Registration certificate owner
- Locking wheel nut
- Card key
- Hook /Hicth ball
- Spare Key
- User manual
- Rear parcel shelf
- Document holder

Main set of tyres

Front Left	FULDA	225/55/17 Summer	6 mm
Front Right	FULDA	225/55/17 Summer	6 mm
Back Left	GOODYEAR	225/55/17 Summer	6 mm
Back Right	GOODYEAR	225/55/17 Summer	6 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat



Front passenger compartment


Front right


Odometer


Navigation


Cable




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other



Other



Loose Items / Locking wheel nut



Roof / - / Scratched



Door sill / Back Left / Scratched



Door panel / Back Left / Dent



Interior tailgate lining / Upper Front / Scratched



Interior tailgate lining / Upper Front / Scratched



Interior tailgate lining / - / Scratched



Interior tailgate lining / - / Scratched



Interior tailgate lining / - / Scratched



Fire extinguisher / - / Non Compliant




Fire extinguisher / - / Non Compliant

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bonnet / - / Paint etching




Bonnet / - / Paint etching



Bonnet / - / Paint etching



Interior complete / - / Stained



Interior complete / - / Stained



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Door / Back Right / Dent



Door / Back Right / Dent



Door / Back Right / Dent



Wing / Front Right / Scratched



Wing / Front Right / Scratched



Rim / Front Right / Scratched




Rim / Front Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Door / Front Right / Dent



Door / Front Right / Dent



Wing / Front Left / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.