


Skoda Superb: 2BUS256

Vinnumber:	TMBJW7NP0N7034911	Versionname:	
First Registrationdate:	29/03/2022	Fiscalpower:	
Expertise Mileage:	133723	Power Kw:	
Bodytype:		Body colour:	Red
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3202
Fueltype:	Hybrid Petrol		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Sun Roof electric:	
Seats F heated:		Panoramic roof:	
Radio multimedia:		Luggage cover:	
Type of headlighting:	Headlighting LED	Front parking sensors:	
Type of GPS:	GPS big screen color	Rear parking sensors:	
Type of Lining:	Lining leather	Type of Tow bar:	Tow bar removable
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection
Tyres

235/40/19/96 W				
Summer tyres:	Fr.L.	Hankook: 6 mm	Fr.R.	Hankook: 6 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				235/40 R 19 96 W
Tyre size FR				235/40 R 19 96 W
Tyre size RL				235/40 R 19 96 W
Tyre size RR				235/40 R 19 96 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Spare wheel:	No	Jack:	No
Emergency spare wheel:	No	Runflat:	No
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		

Total cost ex VAT	1367,48
Centre console, Scratch(es), Acceptable	0,00



Steering wheel, Worn, Acceptable 0,00



Seat cover FL, Worn, Acceptable 0,00



Interior, Not original part, Forfeit 15,00



Bumper F, Scratch(es), Repair and paint (complete) 355,89



Wing FL, Dent(s) and scratch(es), Repair and paint (complete) 429,48



Spare wheel, Missing, Check 0,00



Boot lid covering R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 355,89





Door FR, Scratch(es), Acceptable 0,00



Tyre FR, Tear, Replace 211,22



Wing RR, Repaired, Acceptable 0,00



Bodywork, Not original part, Acceptable 0,00

