DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	ZAC5JACL5 RJL21487	Registration date	28/02/2025	Exterior Color	Unknown
Brand	JEEP	Licence Plate	EU-FA 9995	Odometer	33 649 km
Model	AVENGER 1.2 GSE T3 GDI Altitude				

Inspection Details

Arrival Date	18/08/2026	Inspection ID	7119593	Inspection date	21/08/2026
Assign Date	18/08/2026	Fleet owner	Leasys FINN	Inspection loc.	Leasys AKB Zörbig



Generic equipment

Removable element

Spare wheel kit	✓
Toolkit	✓
Rear parcel shelf	✓
Floor mat B	✓
Floor mat F	✓


Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✓

Tyres

Goodyear 215/60/17 V All seasons 5.0 mm

Goodyear 215/60/17 V All seasons 5.0 mm





Goodyear 215/60/17 V All seasons 6.0 mm

Goodyear 215/60/17 V All seasons 6.0 mm

Exception / Damage

1



Part	Door sill	Repair Time	-	Part Cost	-
Position	Back right	Repair Cost	-	Gross Cost	50.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	50.00€	**Net Cost**	**50.00€**

2



Part	Door	Repair Time	-	Part Cost	-
Position	Front left	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	10.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

3



Part	Wing	Repair Time	-	Part Cost	-
Position	Front right	Repair Cost	-	Gross Cost	-
Damages	Repaired	Paint Time	-	Depreciation %	10.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

4

Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	10.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

5

Part	Bonnet	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	10.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

6

Part	Windscreen	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

7

Part	Bumper	Repair Time	-	Part Cost	-
Position	Back	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	10.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

8

Part	Caisse de chargement complète	Repair Time	-	Part Cost	-
		Repair Cost	-	Gross Cost	-
Position	-	Paint Time	-	Depreciation %	10.00%
Damages	Scratched	Paint cost	-	Depreciation	-
Severity	-	Flat Rate	-	**Net Cost**	**-**
Repair mode	For info				

Summary Inspection

Gross Price	50.00€	Depreciation	-	Net Price	50.00€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	0.00€	0.00	0.00€	-	-	0.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	0.00€	-	-	0.00€
Flat Rate	50.00€	-	-	50.00€