



**Volkswagen Tiguan:**

Vinnumber:	<b>WVGZZZ5NZNW411576</b>	Versionname:	
First Registrationdate:	<b>11/08/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>157610</b>	Power Kw:	
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1730</b>
Fueltype:	<b>Hybrid Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total	<b>1</b>	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Luggage cover	
Type of headlighting	<b>Headlighting LED</b>	Front parking sensors	
Type of GPS	<b>GPS big screen color</b>	Rear parking sensors	
Type of Lining	<b>Lining leather</b>	Type of Tow bar	<b>No Tow bar</b>
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Tyres**

255/45/19/92 H				
Winter tyres:	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>255/45 R 19 92 H</b>
Tyre size FR				<b>255/45 R 19 92 H</b>
Tyre size RL				<b>255/45 R 19 92 H</b>
Tyre size RR				<b>255/45 R 19 92 H</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>264</b>
Tyre make FR				<b>264</b>
Tyre make RL				<b>264</b>
Tyre make RR				<b>264</b>

**Assistance equipment**

Number of charging cables (normal)	<b>1</b>
Number of charging cables (rapid charge)	<b>1</b>

Total cost ex VAT	<b>1664,90</b>
-------------------	----------------

Ignition key, Missing, Replace	<b>350,09</b>
--------------------------------	---------------



Bumper moulding F, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00



Door RL, Dent(s), Acceptable 0,00



Alloy rim FL polished, Deformed / Strained, Repair/replace (lump sum) 150,00



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Tailgate / Boot, Dent(s), Repair and paint (complete) 422,44



Rear window, Scratch(es), Replace 0,00



Wing trim FR, Scratch(es), Acceptable 0,00



Wing FR, Dent(s) and scratch(es), Acceptable 0,00



Door FR, Dent(s) and scratch(es), Repair and paint (complete) 0,00



Door RR, Dent(s), Repair and paint (complete) 445,79



Wing trim RR, Scratch(es), Replace 0,00



Wing RR, Chemical polution, Polish 0,00

