APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	PEUGEOT
Model / version:	308 SW
Vin:	VR3FCYHZLNY554842
Plate:	2CHB796
Mileage:	140782
First registration:	26/07/2022
Color:	Artense Grey

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓


PICTURES














































VIN INFORMATION

depuis 04.22 16585	3-ème période 2021/avant 3-ème période 2023	avertisseur à deux tons
climatisation automatique	condenseur de 19,3 dm² et de 12 mm d'épaisseur	liquide de climatisation R1234YF
Keyless-Go	rétroviseurs électrique, rabattables et chauffants	avertisseur de fatigue
système de navigation	6 haut-parleurs	instruments digitaux
Touchscreen 10"	aide au parking ar	garnissage tissu
équipement Active	volant en cuir multifonctions	Peugeot Connect Assistance
sièges av Confort	réservoir carburant avec protection contre les erreurs de remplissage (Diesel)	radiateur de 28 dm² et de 18 mm d'épaisseur en aluminium
1499 cc (1,5 L) 96 KW YHZ DV5RC	6 vitesses ML6C	suspension normale
système de freinage automatique avec caméra et radar (AEBS3)	colonne de direction réglable en profondeur	barre stabilisatrice av 27.500 Nm
disques de frein av 304 mm	205/55 R 16 .. V	7 J x 16 Alu "Auckland"
7 J x 16 Alu	alternateur 180 A	roue de secours
ventilateur électrique 140 W RB45	5 portes (Wagon)	batterie 70 Ah EFBC
grille de calandre Artense gris	2 couches métallisée	

EQUIPMENT

Board computer: ?

Central locking: ?

Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm	Goodyear	205/55/R16/94V	Summer	Aluminium	×
Front right	5 mm	Goodyear	205/55/R16/94V	Summer	Aluminium	×
Rear left	5 mm	Goodyear	205/55/R16/94V	Summer	Aluminium	×
Rear right	5 mm	Goodyear	205/55/R16/94V	Summer	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Seat cover FR	Dirty
2	Boot lid covering R	Scratch(es)
3	Alloy rim FL	Dent(s) and scratch(es)
4	Door FL	
6	Bumper F	Dent(s) and scratch(es)
7	Outside rear-view mirror L, complete	Grooved

Total: 6

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
5	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Seat cover FR - Dirty




2 - Boot lid covering R - Scratch(es)






3 - Alloy rim FL - Dent(s) and scratch(es)






4 - Door FL




6 - Bumper F - Dent(s) and scratch(es)






7 - Outside rear-view mirror L, complete - Grooved





5 - Bodywork - Dent(s) and scratch(es) - Renta®










SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

22/10/2026 14:39

