
MACADAM







Skoda Superb: Z305RS

Vinnumber:	**TMBJN7NP5R7047565**	Versionname:	**Superb 1.5 TSI ACT 110kW Business Edition combi DSG**
First Registrationdate:	**11/06/2024**	Fiscalpower:	
Expertise Mileage:	**70037**	Power Kw:	**110**
Bodytype:		Body colour	**Magic Black pearlscent**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Petrol**	Parking lot	**610**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**1**	Rear parking sensors	
GPS		Hook	
Autom climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 16 / 99 / V / Aluminium	6,2 mm	Bridgestone	All season
	Right	215 / 60 / 16 / 99 / V / Aluminium	6,8 mm	Bridgestone	All season
Rear	Left	215 / 60 / 16 / 99 / V / Aluminium	7,0 mm	Bridgestone	All season
	Right	215 / 60 / 16 / 99 / V / Aluminium	7,4 mm	Bridgestone	All season

Assistance equipment

Ignition key, Missing, Replace

No pictures to display

Door FL, Dent(s), Repair and paint (complete)





Bumper F, Deformed / Strained, Replace and paint






Bonnet, Scratch(es), Repair and paint (complete)




Wing RR, Scratch(es), Repair and paint (complete)






Bumper R, Scratch(es), Repair and paint (complete)







Tailgate / Boot, Scratch(es), Repair and paint (complete)







Roof, Chemical polution, Repair and paint (complete)




Onderhoudshistorie van: TMBJN7NP5R7047565

ALPHABET

Kenteken	Z305RS
Merk Model	Skoda Superb 1.5 TSI ACT 110kW Business Edition combi DSG
Brandstofsoort	Benzine
Datum deel1	6/11/24

Datum reparatie	Kilometerstand	Reparatie omschrijving
8/12/26	60,457	Bougie
8/12/26	60,457	Onderhoudsbeurt
8/12/26	60,457	Vervanging band
8/12/25	31,567	Onderhoudsbeurt
8/12/25	31,568	Reparatie band(en)
6/13/24	10	Vervanging band