



CITROËN BERLINGO: FB-060-TM

Vinnumber:	VF77DBHY6JJ678968	Versionname:	CITROËN BERLINGO BlueHDi 100 BVM Club M VU [3P] bvm 5-100CH-5cv (fourgonnette-)
First Registrationdate:	14/11/2018	Fiscalpower:	
Expertise Mileage:	104369	Power Kw:	73
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	2	Radio	
Number keys remote	1	Sliding door right-side	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Type of climate control	Manual climate control		

Tyres

	195/65/15/95 H			
Summer tyres:	Fr.L.	Bridgestone: 50%	Fr.R.	Bridgestone: 40%
	Re.L.	Goodyear: 60%	Re.R.	Goodyear: 60%
Tyre profile depth FL				5.0
Tyre profile depth FR				5.5
Tyre profile depth RL				4.4
Tyre profile depth RR				4.2
Tyre size FL				195/65 R 15 95 H
Tyre size FR				195/65 R 15 95 H
Tyre size RL				195/65 R 15 95 H
Tyre size RR				195/65 R 15 95 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
Side wall RL, Dent(s), Repair and paint (complete)			



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, Glue residues, Sticker removal small



Historique Maintenance

Immatriculation: **FB-060-TM** Date de 1ère immatriculation: **14/11/2018**

Modèle: **Citroen BERLINGO BlueHDi 100 BVM Club M VU [3P] bvm 5-100CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
21/05/2026	100.646	GARAGE DEBRIL	Eclairage
			Electricité Consommables
			Essuie - Glace Avant (Remplacement)
			Eclairage
			Ampoule de phare (Remplacement)
			REVISION
			DIVERS CARBURANT
			Liquide ADBLUE (Remplacement)
			Fluide
			Liquide de frein (Remplacement)
			Liquide de frein
			Filtre à carburant (Remplacement)
			Filtre à Carburant
			Additif pour carburant (Contrôle)
			Alimentation
			Filtre à air (Remplacement)
			Antigel (Contrôle)
			Huile Moteur
			Entretien - Standard
			Fluide
			Petite Fourniture moteur
			Filtre à Huile
			LAMPE RPLT
			LAMPE RPLT
			BALAIS ESSUIE GLACE AV
			ADBLUE
			LIQUIDE DE FREIN
			FILTRE A CARBURANT RPLT
			FILTRE A AIR RPLT
			Ampoule (Remplacement)
			LIQUIDE DE REFROIDISSEMENT RPLT
17/07/2025	83.444	GARAGE DEBRIL	DIVERS ELEC

Historique Maintenance

Immatriculation: **FB-060-TM**

Date de 1ère immatriculation: **14/11/2018**

Modèle: **Citroen BERLINGO BlueHDi 100 BVM Club M VU [3P] bvm 5-100CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
16/07/2025	79.574	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
07/02/2025	79.444	GARAGE DEBRIL	DIVERS CLIM
			REVISION
			FILTRE CLIM RPLT
			DISQUES PLAQUETTES AV RPLT
			ADBLUE
			BALAISSUIE GLACE AV
			RECYCLAGE
29/07/2024	75.023	GARAGE DEBRIL	ADBLUE
07/12/2023	67.044	GARAGE DEBRIL	ECLAIRAGE DE PLAQUE RPLT
			LAMPE CODE AVD RPLT
15/11/2023	66.717	GARAGE DEBRIL	BALAISSUIE GLACE AV
			DIVERS CLIM
			REVISION
			RECYCLAGE
			ADBLUE
08/02/2023	52.681	GARAGE DEBRIL	DIVERS ELEC
31/10/2022	48.012	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
			REPLACEMENT PNEUS ETE
19/10/2022	47.721	GARAGE DEBRIL	DIVERS CLIM
			ADBLUE
			BALAISSUIE GLACE AV
			LIQUIDE DE FREIN
			FILTRE A AIR RPLT
			REVISION
			RECYCLAGE
			REVISION
21/07/2022	42.135	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS ETE
16/12/2021	35.161	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
29/06/2021	34.776	GARAGE DEBRIL	LAMPE CODE AVD RPLT
			REVISION
			DISQUES PLAQUETTES AV RPLT

Historique Maintenance

Immatriculation: **FB-060-TM**

Date de 1ère immatriculation: **14/11/2018**

Modèle: **Citroen BERLINGO BlueHDi 100 BVM Club M VU [3P] bvm 5-100CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
			PLAQUETTES AR RPLT
			RECYCLAGE
			BALAIS ESSUIE GLACE AV
			FILTRE CLIM RPLT
13/10/2020	29.085	GARAGE WARME	LAMPE CODE AVD RPLT
31/03/2020	19.801	COPPOLA FLORENT	JANTE RPLT
31/03/2020	19.801	COPPOLA FLORENT	PERMUTATIONS PNEUS
24/01/2020	16.982	NORAUTO SAS (PRODUIT SPE)	REPARATION DE ROUE
30/12/2019	15.954	GARAGE WARME	ADBLUE
			REVISION
			BALAIS ESSUIE GLACE AV
10/12/2019	14.914	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS HIVER
			PERMUTATIONS PNEUS
17/05/2019	6.718	NORAUTO SAS (PRODUIT SPE)	PERMUTATIONS PNEUS
05/02/2019	2.300	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS HIVER
28/01/2019	1.943	EUROMASTER FRANCE	PERMUTATIONS PNEUS