



HYUNDAI TUCSON: GG-743-EJ

Vinnumber:	TMAJE811BMJ090405	Versionname:	HYUNDAI TUCSON 1.6 HYBRID 230 EXECUTIVE VP [5P] bva 6-230CH-10cv (SUV)
First Registrationdate:	5/05/2022	Fiscalpower:	
Expertise Mileage:	69885	Power Kw:	169
Bodytype:	Off-road	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Grey
Fueltype:	Hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Anthraccite
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Headlights Xenon/LED/Laser	
Steering wheel leather		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of climate control	Autom climate control	Rear view camera	
		Seat cover lining	Lining Leather

Tyres

	235/50/19/103 W			
Summer tyres:	Fr.L.	Falken: 50%	Fr.R.	Falken: 55%
	Re.L.	Michelin: 75%	Re.R.	Michelin: 75%
Tyre profile depth FL				4.8
Tyre profile depth FR				4.6
Tyre profile depth RL				3.4
Tyre profile depth RR				3.2
Tyre size FL				235/50 R 19 103 W
Tyre size FR				235/50 R 19 103 W
Tyre size RL				235/50 R 19 103 V
Tyre size RR				235/50 R 19 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				1957074
Tyre make FR				1957074
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Inner door sill RL, Dent(s) and scratch(es), Repair and paint (complete)			



Floor mat F, Tear, Replace



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Door RL, Scratch(es), Paint



Door trim RR, Unclashed, Dismount/Mount



Luggage compartment cover, Missing, Replace



Rear roof pillar covering L, Scratch(es), Replace



Rear roof pillar covering R, Scratch(es), Replace



Internal boot lining L, Scratch(es), Replace



Internal boot lining R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Bumper spoiler Rear, Deformed / Strained, Replace



Boot lid covering R, Scratch(es), Replace



Historique Maintenance

Immatriculation: **GG-743-EJ** Date de 1ère immatriculation: **05/05/2022**

Modèle: **Hyundai TUCSON 1.6 HYBRID 230 EXECUTIVE VP [5P] bva 6-230CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
07/10/2025	52.778	IMAC 2	REVISION
	0		DIVERS ELEC
18/10/2024	35.409	IMAC 2	REVISION ET CLIM
	0		LIQUIDE DE FREIN
	0		LIQUIDE LAVE GLACE
03/08/2023	18.223	IMAC 2	REVISION