



IDENTIFICATION VEHICLE

Driver name:
Make: VOLKSWAGEN
Model / version: GOLF VARIANT VIII
Vin: WVVZZZCDZNW534619
Plate: 2CEN778
Mileage: 155401
First registration: 24/06/2022
Color: DOLPHIN GREY



ADDITIONAL INFORMATION


Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✖
Registration certificate: ✖
Registration certificate 2: ✖
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✔

PICTURES





VIN INFORMATION

Radio
Bluetooth
Projecteurs à allumage automatique
Diamètre avant 16
Largeur arrière 7,0
Hauteur avant 55
Indice de vitesse arrière V
Chauffage supplémentaire
Accoudoir central arrière
1968 cm3
150 ch
Freins avant à disques
Rétroviseur droit chauffant

Siège avant gauche chauffant
Sièges avant à réglage électrique
Sièges avant à réglage lombaire
Fixations Isofix siège passager avant
Volant chauffant
Aide au stationnement arrière
Caméra arrière de recul

Verrouillage centralisé à commande à distance
Lunette arrière teintée foncée
détecteur de pluie essuie-vitre

Témoin d'oubli de ceinture arrière

Avertisseur d'angle mort
poignées de portes éclairée
radio digitale (DAB)
filet de séparation

Radio avec système de navigation
Transmission séquentielle
Matière : alliage
Diamètre arrière 16
Diamètre avant 16
Hauteur arrière 55
Largeur avant 205
Climatisation automatique
Finition intérieure chrome
2.00 litres
Euro 6
Freins arrière à disques
Rétroviseurs rabattables électriques

Sièges avant chauffants
Siège avant gauche à réglage mémorisé
Sièges avant massants
Garnitures tissu
Volant multifonction
Assistance au parking
Régulateur automatique de la distance

Carte mains libres

Vitres portes arrière teintées foncées
Ceintures de sécurité arrière centrale à enrouleur
Assistant maintien de la voie

depuis 04.22
antenne AM/FM
services Online
suspension ar à 4 bras

7 haut-parleurs
7 rapports
Lettre repère (J)
Largeur avant 7,0
Diamètre arrière 16
Indice de vitesse avant V
Largeur arrière 205
Accoudoir central avant
Diesel
110 kw
Métallisée vernissée
Rétroviseur gauche chauffant
Rétroviseur intérieur jour/nuit automatique
Siège avant gauche à réglage électrique
Siège avant gauche à réglage lombaire
Sièges arrière chauffants
Volant cuir
Aide au stationnement avant
Caméra avant
Affichage lecture des panneaux de signalisation
Appel de secours

Vitres de custode teintées foncées
Témoin d'oubli de ceinture avant

Freinage d'urgence assistée autonome (urbain)
Digital Cockpit Pro
Car2X communication
éclairage d'ambiance
entretien à intervalle flexible (Long Life)
Q16

traitement des gaz d'échappement avec
catalyseur SCR

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer		?
Front right	5 mm			Summer		?
Rear left	5 mm			Summer		?
Rear right	5 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Certificate of registration (customer) 1	Not original part
3	Certificate of conformity	Missing
4	Contact key	Damaged
5	Seat cover FL fabric	Stain
7	Windscreen	Crack
8	Bumper R	Scratch(es)
9	Wing RR	Dent(s) and scratch(es)
10	Outer sill R	Blistering
11	Alloy rim FR	Scratch(es)

Total: 9


ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Certificate of registration (customer) 2	Missing	✓	✗	✗
6	Bodywork	Damaged	✓	✗	✗


Total: 2

DAMAGES DETAILS



1 - Certificate of registration (customer) 1 - Not original part



3 - Certificate of conformity - Missing



4 - Contact key - Damaged



5 - Seat cover FL fabric - Stain




7 - Windscreen - Crack



8 - Bumper R - Scratch(es)




9 - Wing RR - Dent(s) and scratch(es)




10 - Outer sill R - Blistering





11 - Alloy rim FR - Scratch(es)



2 - Certificate of registration (customer) 2 - Missing - Renta®



6 - Bodywork - Damaged - Renta®



SIGNATURE

Expert
02/07/2026 14:55