



BMW X1 (UKL): 2CHN907

Vinnumber:	WBA71AB0305V32082	Versionname:	X1 (F48) 25e xDrive 1.5i 220pk/cv 5p Aut.
First Registrationdate:	1/08/2022	Fiscalpower:	
Expertise Mileage:	73809	Power Kw:	92
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Maintenance	plus 31000 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/55/17/101 Y				
Summer tyres:	Fr.L.	Firestone: 7 mm	Fr.R.	Firestone: 7 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/55 R 17 101 Y
Tyre size FR				225/55 R 17 101 Y
Tyre size RL				225/55 R 17 101 Y
Tyre size RR				225/55 R 17 101 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				258
Tyre make FR				258
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Registration document, Missing, Replace



Certificate Of Conformity, Missing, Replace



Bumper F, Repaired, Check



Door FL, Scratch(es), Acceptable



Door RL, Dent(s), Acceptable



Tailgate / Boot, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Acceptable



Door RR, Dent(s), Acceptable



Door FR, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable



Kenteken	2CHN907
Merk Model	BMW X1 (F48) 25e xDrive 1.5i 220pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	8/1/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/20/26	72,440	batterij	Vervangen
5/20/26	72,440	BMW/MINI service standaard omvang	Uitvoeren
5/20/26	72,440	BMW/MINI service voertuig-check	Uitvoeren
5/20/26	72,440	bougie	Vervangen
5/20/26	72,440	klein materiaal	
5/20/26	72,440	koelwatervloeistof	Bijvullen/-laden
5/20/26	72,440	ruitwisserrubber achter	Vervangen
5/20/26	72,440	ruitwisservloeistof	Bijvullen/-laden
5/20/26	72,440	service luchtfilter	Uitvoeren
5/20/26	72,440	service microfilter	Uitvoeren
5/20/26	72,440	service motorolie	Uitvoeren
5/14/25	52,434	BMW/MINI service standaard omvang	Uitvoeren
5/14/25	52,434	controle niveaus	Uitvoeren
5/14/25	52,434	klein materiaal	
5/14/25	52,434	remvloeistof	Vervangen
5/14/25	52,434	ruitwisserrubber vooraan	Vervangen
5/30/24	36,892	service microfilter	Uitvoeren
5/30/24	36,892	service motorolie	Uitvoeren