



IDENTIFICATION VEHICLE

Driver name: HM Tongeren
Make: BMW
Model / version: X1
Vin: WBA71AB0605V04440
Plate:
Mileage: 81147
SOH:
First registration: 18/03/2022
Color: Saphirschwar





ADDITIONAL INFORMATION





Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

Radio
8 rapports
Projecteurs antibrouillard à LED
Lettre repère (J)
Largeur avant 7,5
Diamètre arrière 17
Indice de vitesse avant H
Largeur arrière 225
Accoudoir central avant
1.50 litre
Métallisée vernissée
Rétroviseur gauche jour/nuit automatique

Système navigation
4 roues motrices
Équipement Advantage
Diamètre avant 17
Largeur arrière 7,5
Hauteur avant 55
Indice de vitesse arrière H
Climatisation automatique
Hybride essence
92 kw
Rétroviseur gauche chauffant
Rétroviseur droit jour/nuit automatique

Transmission automatique
Projecteurs à LED
Matière : alliage
Diamètre arrière 17
Diamètre avant 17
Hauteur arrière 55
Largeur avant 225
Climatisation réfrigérant 1234YF
1499 cm3
125 ch
Rétroviseur droit chauffant
Rétroviseurs rabattables électriques

Rétroviseur intérieur jour/nuit automatique	Siège avant gauche à réglage lombaire	Sièges avant à réglage lombaire
Garnitures simili-cuir	Volant cuir	Volant sport
Volant multifonction	Aide au stationnement avant	Aide au stationnement arrière
Assistance au parking	Caméra avant	Caméra arrière de recul
Régulateur automatique de la distance	Affichage tête haute	Ouverture du coffre électriquement
Alarme	Appel de secours	Lunette arrière teintée foncée
Vitres portes arrière teintées foncées	Vitres de custode teintées foncées	Fixotoit noir
Protection piéton	Freinage d'urgence assistée autonome (urbain)	Avertisseur de collision avant
Contrôle pression des pneus	depuis 10.21	mesures CO2 étendues
Teleservices	tuner DAB	Connected Drive Services
protection acoustique des piétons	pack de rangement	boulons antivol de roue
encarts intérieurs oxyde d'argent foncé	spécifique Europe	
mat avec accents noir brillant		

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✗	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✗
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	6 mm		225/55R17	Winter		?
Front right	6 mm		225/55R17	Winter		?
Rear left	6 mm		225/55R17	Winter		?
Rear right	6 mm		225/55R17	Winter		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Contact key - Boordcomputer resetten	Not original part
3	Door FL	Grooved
4	Inner door sill RL	Dent(s)
5	Wing RL	Dent(s) and scratch(es)
6	Bumper R	Dent(s) and scratch(es)
7	Wing RR	Dent(s)
8	Door RR	Dent(s) and scratch(es)

Total: 7

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Contact key - Boordcomputer resetten - Not original part



3 - Door FL - Grooved



4 - Inner door sill RL - Dent(s)



5 - Wing RL - Dent(s) and scratch(es)




6 - Bumper R - Dent(s) and scratch(es)



7 - Wing RR - Dent(s)



8 - Door RR - Dent(s) and scratch(es)



2 - Bodywork - Dent(s) and scratch(es) - Renta®

