



CITROËN BERLINGO: FL-895-EX

Vinnumber:	VR7EFYHYCKN558740	Versionname:	CITROËN BERLINGO M 1000kg BlueHDi 100 S&S
First Registrationdate:	29/10/2019		BVM Driver VU [4P] bvm 5-100CH-5cv
Expertise Mileage:	62284		(fourgonnettesimple cabine)
Bodytype:	Transporter	Fiscalpower:	75
Gearbox:	MAN 5 VIT	Power Kw:	White
Transmission:	Front	Body colour:	Opaque
Fueltype:	Diesel	Paint type:	Dark Grey
Engine functioning:	Yes	Interior colour:	Steel
Battery functioning:	Yes	Type of rims (mounted):	Steel
Vehicle running:	Yes	Dashboard color:	Black
Number of doors:	4		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Sliding door right-side	
Steering wheel multifunctional		Rear view camera	
Type of climate control	Manual climate control	Seat cover lining	Lining Other

Tyres

	205/60/16/96 H			
Summer tyres:	Fr.L.	Michelin: 25%	Fr.R.	Michelin: 25%
	Re.L.	Michelin: 20%	Re.R.	Michelin: 20%
Tyre profile depth FL				6.7
Tyre profile depth FR				6.7
Tyre profile depth RL				6.8
Tyre profile depth RR				6.9
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Seat cover FR, Stain, Cleaning



Seat cover FL, Stain, Cleaning



Centre console, Scratch(es), Acceptable



Floor mat F, Tear, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Remote ignition key, Missing, Repair/replace (lump sum)



Steel rim FL, Deformed / Strained, Replace



Bumper F, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Fog lamp L, Unclassped, Dismount/Mount



Rear light L, Broken, Replace



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper corner RL, Deformed / Strained, Repair and paint (complete)



Bodywork, Not original part, Remove lettering



Numéro d'identification du véhicule: VR7EFYHYCKN558740

Modèle: CITROËN BERLINGO M 1000kg BlueHDi 100 S&S BVM Driver VU [4P]
bvm 5-100CH-5cv (fourgonnettesimple cabine)

Date de 1ère immatriculation: 29/10/2019

Immatriculation: FL-895-EX

Date	Descriptif	Kilométrage
08/11/2023	CONTRÔLE CIRCUIT REFROIDISSEMENT (intervention)	44 644
08/11/2023	Filtre à Air/Gasoil (Rempl/jeu)	
08/11/2023	LIQUIDE FREIN (rempl./1)	
08/11/2023	MICRO FILTRE CLIMATISATION (rempl./1)	
08/11/2023	REVISION 2 ANS (intervention)	

Date	Descriptif	Kilométrage
13/05/2025	LECTURE DES MEMOIRES (intervention)	55 586
13/05/2025	TELECHARGEMENT CALCULATEUR (intervention)	