



CITROËN C4: 7253-MBB

Vinnumber:	VR7BBYHSANE052382	Versionname:	Citroen BlueHdi 110 S&S Feel Pack berlina con portón 81kW 5P manual
First Registrationdate:	7/09/2022	Fiscalpower:	
Expertise Mileage:	157314	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	2	Central consol F:	
Number keys remote:	1	Luggage cover:	
GPS big screen color:		Rear parking sensors:	
Windows electric F:			
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Steering wheel leather:			
Radio multimedia:			
Type of climate control:	Autom climate control		

Tyres

195/60/18/96 H				
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm
Tyre profile depth FL:				6.0
Tyre profile depth FR:				6.0
Tyre profile depth RL:				3.0
Tyre profile depth RR:				3.0
Tyre size FL:				195/60 R 18 96 H
Tyre size FR:				195/60 R 18 96 H
Tyre size RL:				195/60 R 18 96 H
Tyre size RR:				195/60 R 18 96 H
Tyre make FL:				259
Tyre make FR:				259
Tyre make RL:				259
Tyre make RR:				259

Assistance equipment

Repair kit:	Yes
Interior, Dirty, Cleaning	





Registration document, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Vanity mirror, Unclashed, Dismount/Mount



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Acceptable



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper F, Scratch(es), Repair and paint (complete)





Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door trim FR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door trim RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper R, Scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

