



Peugeot 2008: R296HX

Vinnnumber:	VR3UKZKXZJ724280	Versionname:	e-2008 100kW/ 50kWh Active Pack
First Registrationdate:	25/10/2022	Fiscalpower:	
Expertise Mileage:	150418	Power Kw:	100
Bodytype:		Body colour:	Blanc Nacre metaallak
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	611
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Rear parking sensors
GPS		
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 65 / 16 / 98 / H / Aluminium	3,5 mm	Continental	Summer
	Right	215 / 65 / 16 / 98 / H / Aluminium	3,5 mm	Continental	Summer
Rear	Left	215 / 65 / 16 / 98 / H / Aluminium	4,0 mm	Continental	Summer
	Right	215 / 65 / 16 / 98 / H / Aluminium	3,2 mm	Continental	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Service, Maintenance, Execute



Interior, Dirty, Cleaning



Wing FL, Dent(s), Repair and paint (complete)



Door FL, Dent(s), Repair and paint (complete)



Door RL, Dent(s), Repair and paint (complete)



Bumper F, Stone chip(s), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Replace and paint



Roof, Dent(s), Repair and paint (complete)



Kenteken	R296HX
Merk Model	Peugeot e-2008 100kW/ 50kWh Active Pack
Brandstofsoort	Elektrisch
Datum deel1	25-10-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
11-11-25	126.456	Onderhoudsbeurt
11-11-25	126.456	Tankklep
19-05-25	107.890	Tankklep
13-05-25	107.789	Onderhoudsbeurt
19-11-24	88.187	Onderhoudsbeurt
19-11-24	88.187	Remvloeistof
19-11-24	88.187	Ruitenwischerblad(en) voorzijde
09-07-24	72.000	Vervanging band
28-05-24	69.417	Onderhoudsbeurt
07-12-23	48.048	Onderhoudsbeurt
23-05-23	25.702	Onderhoudsbeurt
23-05-23	25.702	Ruitenwischerblad(en) voorzijde
09-02-23	13.402	Onderhoudsbeurt