

INSPECTION REPORT


End of contract

GENERAL INFO

File	312873
License plate	2GME693
Vehicle identification number	VR7ACYHZ9RL027865
Dossier	2023355210
Make	Citroen C5 Aircr.1.5BHDi 130 P
Mileage	19024
First registration	27/01/2025
client availability date	13/05/2026
inspectionDate	19/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
19	Bumper Front / Lower Cover Not Painted / Replace	Y
80	Door Front Left // Smart Repair Small	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
193	Door Rear Right // Painting	Y
197	Door Rear Right / Trim / Replace	Y
213	Door Front Right // Painting	Y
217	Door Front Right / Trim / Replace	Y

Damage Pictures



Bumper Front / Lower Cover Not Painted / Replace-scratch



Door Front Right / Trim / Replace-scratch



Door Front Right // Painting-scratch



Door Rear Right // Painting-scratch



Door Rear Right / Trim / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Front Left // Smart Repair Small-scratch