MACADAM










Mazda CX-5: KDZ31L

Vinnumber:	**YCMKM0CB500101813**	Versionname:	**CX-5 2.5 E-skyactiv-G 104kW MHEV Homura automaat**
First Registrationdate:	**2/04/2026**	Fiscalpower:	
Expertise Mileage:	**11795**	Power Kw:	**104**
Bodytype:		Body colour	**Machine Grey Metallic**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Hybrid Petrol**	Parking lot	**634**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Lining leather	
GPS		Rear parking sensors	
Autom climate control		Hook	
Radio multimedia		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 55 / 19 / 99 / V / Aluminium	6,2 mm	Bridgestone	Summer
	Right	225 / 55 / 19 / 99 / V / Aluminium	6,6 mm	Bridgestone	Summer
Rear	Left	225 / 55 / 19 / 99 / V / Aluminium	7,0 mm	Bridgestone	Summer
	Right	225 / 55 / 19 / 99 / V / Aluminium	7,0 mm	Bridgestone	Summer

Assistance equipment

Number of charging cables (rapid charge)	**0**

Door FL, Scratch(es), Repair and paint (complete)




Door trim FL, Scratch(es), Replace and paint




Bumper FM, Scratch(es), Repair and paint (complete)




Wing RR, Dent(s), Repair and paint (complete)





Outside rear-view mirror housing R, Scratch(es), Polish




Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)







Bumper corner RR, Scratch(es), Repair and paint (complete)




Bumper RM, Scratch(es), Repair and paint (complete)




Bumper trim R, Scratch(es), Replace




Onderhoudshistorie van: YCMKM0CB500101813

ALPHABET

Kenteken	KDZ31L
Merk Model	Mazda CX-5 2.5 E-skyactiv-G 104kW MHEV Homura automaat
Brandstofsoort	Benzine
Datum deel1	4/2/26

Datum reparatie	Kilometerstand	Reparatie omschrijving
9/2/26	10,225	Reparatie band(en)
6/19/26	925,878	Reparatie band(en)