



BMW 1 Reeks (UKL): 2AQW347

Vinnnumber:	WBA7K110107J22237	Versionname:	116i (F40) 1.5i 109pk/cv 5p
First Registrationdate:	16/06/2021	Fiscalpower:	
Expertise Mileage:	81883	Power Kw:	80
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	NOT OK		
Maintenance	sinds 240 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	195/60/16/89 H			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/60 R 16 89 H
Tyre size FR				195/60 R 16 89 H
Tyre size RL				195/60 R 16 89 H
Tyre size RR				195/60 R 16 89 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Service, Maintenance, Check



Interior, Dirty, Cleaning



Roof liner, Scratch(es), Smart repair



GPS, Scratch(es), Acceptable



Door panel FL, Burned, Smart repair



Steering wheel, Worn, Acceptable



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)





Bumper spoiler F, Scratch(es), Smart repair



Bonnet, Repaired, Check



Door FL, Dent(s), Acceptable



Roof pillar L, Dent(s), Paintless dent repair



Step L, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Smart repair



Step R, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Tyre FR, Tear, Replace



Door FR, Dent(s), Paintless dent repair



Sill trim R, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Check



Kenteken	2AQW347
Merk Model	BMW 116i (F40) 1.5i 109pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	6/16/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/16/26	79,398	BMW/MINI voertuigcontrole	Uitvoeren
4/16/26	79,398	service motorolie	Uitvoeren
8/16/24	56,718	BMW/MINI service standaard omvang	Uitvoeren
8/16/24	56,718	BMW/MINI voertuigcontrole	Uitvoeren
8/16/24	56,718	bougie	Vervangen
8/16/24	56,718	remblokken vooraan	Vervangen
8/16/24	56,718	remvloeistof	Vervangen
8/16/24	56,718	service luchtfilter	Uitvoeren
8/16/24	56,718	service microfilter	Uitvoeren
8/16/24	56,718	service motorolie	Uitvoeren
2/1/24	43,662	BMW/MINI service standaard omvang	Uitvoeren
2/1/24	43,662	klein materiaal	Uitvoeren
2/1/24	43,662	remblokken achter	Vervangen
2/10/23	24,542	batterij	Vervangen
2/10/23	24,542	service microfilter	Uitvoeren
2/10/23	24,542	service motorolie	Uitvoeren